

Linda McCulloch, Superintendent Office of Public Instruction PO Box 202501

#### MONTANA HIGHWAY PATROL

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

TR-13 Revised 11/04

Helena, MT 59620-2501 This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected. Instructions to OPI from School District: ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records. Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction. OPI County # and County Name District Name **Plains Public Schools** 45 Sanders Vehicle I.D. # (VIN) - Entire Number Model Year License # Rated Capacity \*\*\*\*\* 1GBHG31R211966892 2001 250 Bus Type: (see ? for definition) Chassis Make Body Make ✓ A □ B □ C  $\Box$  D Other Chevrolet Wheel Chair Lift Equipped? Wheel Chair Lift Equipped? ☐ Yes ✓ No ☐ Forward Facing ☐ Aisle Facing ✓ Not Applicable Type of Fuel: Is Bus: District Owned Contractor Owned If contractor owned, contractor's name is: ✓ Gas Diesel Other Revier Transportation INSPECTION TO BE FILLED OUT BY THE HIGHWAY PATROL 1st semester ✓ 2nd semester This inspection is for: Approved Approved NΑ Items listed in the Standards Items listed in the Standards Page No NA Page Yes No Yes Corr No.\* for School Buses in Montana No.\* for School Buses in Montana Belt cutter \*\*\*\* attached C17 Identification - front C34 C18 Head lamps C18 Interior lamps C18 Ceiling - interior C10 Color Turn signal lamps - front C18 C21 Seating Turn signal lamps - side (post 1987) C14 C18 Floor C18 Red amber signals - front C9 Aisle C18 Marker lamps - front C22 Tools - storage C18 Windshield C24 Windows C24 Windshield wipers C13 Warning device C20 Exterior mirrors C13 Buzzer emergency door C3 C12 Emergency door Battery C4 Generator or alternator C18 Red amber signals - rear Turn signal lamps - rear C11 C18 Service door Head lamp indicator C18 Stop lamps C6C6 C18 Marker lamps - rear Horn C20 Interior mirror C19 Strobe light - rear \*\*\* C6 Speedometer C17 Identification - rear Brakes C4 Exhaust system (no leaks) Driver seat belt Fuel tank Tires (2/32" rear - 4/32" front min.) Steering gear Fire extinguisher (5 lbs) Cleanliness C13 First aid kit C22 Stop arm No trailer hitch C13 Body fluids kit C5 C11 Defroster Required by forest regulation: C6 Heaters Shovel (securely fastened) C20 Wheelchair forward facing (post 1993) Axe (securely fastened) \*Page number reference, Standards for School Buses in Montana (2002 Edition). \*\*\*\*Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver. 
\*\*Does not apply. \*\*\*New buses ordered after 08/15/02.\*\*\*\*\*Based on original capacity listed on the manufacturers certification tag found inside the bus. On first inspection, this bus is: On reinspection, this bus is: Approved Approved Not Approved Not Approved Inspecting Patrol Officer: Inspecting Patrol Officer: Date Date

Badge No.



# **MONTANA HIGHWAY PATROL**

**School Bus Inspection** School Year 2006

State	
District	
County	
Patrol	
Contractor	

TR-13 Revised 11/04

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the

Highw	ay Patrol as soon as all defects are correct	ted.						•			•		
Instru	actions to OPI from School District:	1											
	s bus has been sold, retired, or is no longe ase make corrections noted below. Don't							action					
					District Name								
0	•					2.0							
Vobio	45 Sanders le I.D. # (VIN) - Entire Number		Ma	odel Ye	or	Licen		ains Publ	Rated C		, ****		
venic	ie i.b. # (VIIV) - Entile Numbei		IVIC	ouel re	aı	Licen	Se #		Kaleu C	араспу	1		
	1T75T4B2151132638			199			J744				78		
Chas	sis Make			B	Body Mal	ке		Bus Type:	: (see ? fo	or defin	ition)		
	Thomas					The	omas	□ A □	□В [	□С	<b>✓</b> D		
Whee	el Chair Lift Equipped?	Whe	el Chai	r Lift Ed	quipped?	)							
□ Y	es 🗹 No	□ F	orwar	d Fac	ing	☐ Aisl	e Facing 🗹 N	ot Applica	able				
Туре	of Fuel:	Is B	us:	Distric	t Owned	√ C	ontractor Owned If co			ractor's	name	is:	
ПС	as ☑ Diesel ☐ Other						Davies Tresses	4					
							Revier Transp	ortation					
		т	) RF FI	LLED		CTION	GHWAY PATROL						
	This	inspect				t semes		ster					
				roved							App	roved	
Page	Items listed in the Standards	Yes	No	NA **	Corr	Page	Items listed in			Yes	No	NA	Corr
No.*	for School Buses in Montana			-^-		No.*	for School Bus		na			<u> </u>	+
C17	Identification - front Head lamps					C18	Belt cutter **** attach Interior lamps	leu				+	+
C10	Color					C18	Ceiling - interior						†
C18	Turn signal lamps - front					C21	Seating						
C18	Turn signal lamps - side (post 1987)					C14	Floor					<b>↓</b>	
C18	Red amber signals - front  Marker lamps - front					C9 Aisle C22 Tools - storage					+	_	
C18	Windshield					C24	Windows					+	+
C24	Windshield wipers					C13	Warning device					†	
C20	Exterior mirrors					C13	Buzzer emergency de	oor					
C3	Battery					C12	Emergency door					<u> </u>	
C4 C11	Generator or alternator Service door					C18	Red amber signals - Turn signal lamps - re					+	+
C6	Head lamp indicator					C18	Stop lamps	Cai				+	+
C6	Horn					C18	Marker lamps - rear						
C20	Interior mirror					C19	Strobe light - rear ***						
C6 C2	Speedometer	<u> </u>				C17	Identification - rear	ooko)				<del>                                     </del>	+
C21	Brakes Driver seat belt					C5	Exhaust system (no l	eaks)				+	+
C7	Steering gear					C7	Tires (2/32" rear - 4/3	32" front min	.)			†	
C13	Fire extinguisher (5 lbs)						Cleanliness						
C13	First aid kit					C22	Stop arm					<u> </u>	
C13	Body fluids kit  Defroster					C5	No trailer hitch  Required by forest r	equiation:				+	
C6	Heaters						Shovel (securely fast	_				+	+
C20	Wheelchair forward facing (post 1993)						Axe (securely fastene	ed)					
	umber reference, Standards for School Buses in I not apply. ***New buses ordered after 08/15/02.**									d nearby	driver.		
On fi	rst inspection, this bus is:					On re	einspection, this bus	is:					
	Approved						Approved	-					
	Not Approved						Not Approved						
Inspe	cting Patrol Officer:					Inspe	cting Patrol Officer:						
Badge	• No	Date				Badge No Date							
Signa	ture of District Official					Date							



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Holona, MT 59620-2501

## **MONTANA HIGHWAY PATROL**

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

Helena, MT 59620-2501 This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected. Instructions to OPI from School District: ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records. Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction. OPI County # and County Name District Name **Plains Public Schools** 45 Sanders Vehicle I.D. # (VIN) - Entire Number Model Year Rated Capacity \*\*\*\*\* License # 1BABABPA33F207134 2003 660 Bus Type: (see ? for definition) Chassis Make Body Make  $\Box$  A  $\Box$  B  $\Box$  C **✓** D **Bluebird** American Wheel Chair Lift Equipped? Wheel Chair Lift Equipped? ☐ Yes ✓ No ☐ Forward Facing ☐ Aisle Facing ✓ Not Applicable Type of Fuel: Is Bus: District Owned Contractor Owned If contractor owned, contractor's name is: Gas ✓ Diesel Other Revier Transportation INSPECTION TO BE FILLED OUT BY THE HIGHWAY PATROL 1st semester ✓ 2nd semester This inspection is for: Approved Approved NΑ Items listed in the Standards Items listed in the Standards Page No NA Yes No Yes Page Corr No.\* for School Buses in Montana No.\* for School Buses in Montana Belt cutter \*\*\*\* attached C17 Identification - front C34 C18 Head lamps C18 Interior lamps C18 Ceiling - interior C10 Color Turn signal lamps - front C18 C21 Seating Turn signal lamps - side (post 1987) C14 C18 Floor C18 Red amber signals - front C9 Aisle C18 Marker lamps - front C22 Tools - storage C18 Windshield C24 Windows C24 Windshield wipers C13 Warning device C20 Exterior mirrors C13 Buzzer emergency door C3 C12 Emergency door Battery C4 Generator or alternator C18 Red amber signals - rear Turn signal lamps - rear C11 C18 Service door C18 Stop lamps C6Head lamp indicator C6 C18 Marker lamps - rear Horn C20 Interior mirror C19 Strobe light - rear \*\*\* C6 Speedometer C17 Identification - rear Brakes C4 Exhaust system (no leaks) Driver seat belt Fuel tank Tires (2/32" rear - 4/32" front min.) Steering gear Fire extinguisher (5 lbs) Cleanliness C13 First aid kit C22 Stop arm No trailer hitch C13 Body fluids kit C5 C11 Defroster Required by forest regulation: C6 Heaters Shovel (securely fastened) C20 Wheelchair forward facing (post 1993) Axe (securely fastened) \*Page number reference, Standards for School Buses in Montana (2002 Edition). \*\*\*\*Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver. 
\*\*Does not apply. \*\*\*New buses ordered after 08/15/02.\*\*\*\*\*Based on original capacity listed on the manufacturers certification tag found inside the bus. On first inspection, this bus is: On reinspection, this bus is: Approved Approved Not Approved Not Approved Inspecting Patrol Officer: Inspecting Patrol Officer: Date Date Badge No.



# **MONTANA HIGHWAY PATROL**

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

TR-13 Revised 11/04

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Highway Patrol as soon as all defects are corrected.													
Instructions to OPI from School District:													
This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.													
Please make corrections noted below. Don't black out the error, OPI may no						eed to read it to make the correction.							
OPI County # and County Name					Distri	ct Name							
	45 Con done						DI	da Bulalia	0-11-				
Vahio	45 Sanders		Ma	dal V		Licon		ains Public	Rated Capacit	*****			
venic	le I.D. # (VIN) - Entire Number		IVIC	odel Ye	ear	Licen	se #		Rated Capacit	y			
	1T79N3B21P1113780			199	92		E28			66			
Chas	sis Make		•	I	Body Mal	ke		Bus Type: (	see ? for defir	ition)			
	<b>T</b> l							$\Box$ A $\Box$	в □с	<b>✓</b> D	i		
\\/hoc	Thomas  I Chair Lift Equipped?	\\/ha	ol Chair	r I ift 🗆	quipped?		omas		<u> </u>				
□ Ye	es 🗹 No		orwar	d Fa	cing	_ Aisl	e Facing 🔛 N	ot Applicab	le				
Туре	of Fuel:	Is B	us:	Distri	ct Owned	d 🗸 Co	ontractor Owned If co	ontractor owne	ed, contractor	s name	is:		
□G	as ☑ Diesel ☐ Other						Davies Treses						
							Revier Transp	ortation					
		т.	DE EU	ED		CTION	CUMAY DATEOL						
	Thio	inspect					GHWAY PATROL ster ✓ 2nd seme	otor					
	THIS	inspeci		roved	18	st semes	iter 💌 zna seme	ster		Λnr	oroved		
Page	Items listed in the Standards	Yes	No	NA	Corr	Page	Items listed in	the Standards	Yes	No	NA	Corr	
No.*	for School Buses in Montana			**	00	No.*	for School Bus				**	00	
C17	Identification - front					C34	Belt cutter **** attach	ed					
C18	Head lamps					C18	Interior lamps						
C10	Color					C18	Ceiling - interior						
C18	Turn signal lamps - front					C21	Seating				<u> </u>		
C18	Turn signal lamps - side (post 1987)				_	C14	Floor				+		
C18	Red amber signals - front  Marker lamps - front				_	C9 Aisle C22 Tools - storage				+	+		
C18	Windshield				+	C24	Windows			+	+		
C24	Windshield wipers					C13	Warning device				+		
C20	Exterior mirrors					C13	Buzzer emergency de	oor			1		
C3	Battery					C12	Emergency door						
C4	Generator or alternator					C18	Red amber signals -						
C11	Service door					C18	Turn signal lamps - re	ear					
C6	Head lamp indicator					C18	Stop lamps						
C6 C20	Horn Interior mirror					C18 C19	Marker lamps - rear Strobe light - rear ***			+	+		
C6	Interior mirror Speedometer						Identification - rear				+-		
C2	Brakes		1	1	+	C4	Exhaust system (no l	eaks)		+	+	+	
C21	Driver seat belt					C5	Fuel tank				+		
C7	Steering gear		1	1		C7	Tires (2/32" rear - 4/3	2" front min.)		1	1		
C13	Fire extinguisher (5 lbs)						Cleanliness						
C13	First aid kit					C22	Stop arm						
C13	Body fluids kit					C5	No trailer hitch						
C11	Defroster				_		Required by forest i						
C6	Wheelsheir forward feeing (post 1003)		1	1			Shovel (securely fast			+	┼	+	
*Page n	Wheelchair forward facing (post 1993) umber reference, Standards for School Buses in N	Montana /	(2002 E4	ition) '	****Bus dri	vers are r	Axe (securely fastene		attached nearh	v driver		1	
	not apply. ***New buses ordered after 08/15/02.**									y univer.			
On fi	st inspection, this bus is:					On re	inspection, this bus	is:					
	Approved						Approved						
	Not Approved						Not Approved						
Inspec	cting Patrol Officer:					Inspec	cting Patrol Officer:						
Badge		Date					e No		Date _				
Signa	Signature of District Official					Date							



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Holona, MT 59620-2501

#### **MONTANA HIGHWAY PATROL**

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

TR-13 Revised 11/04

Helena, MT 59620-2501 This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected. Instructions to OPI from School District: ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records. Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction. OPI County # and County Name District Name **Plains Public Schools** 45 Sanders Vehicle I.D. # (VIN) - Entire Number Model Year License # Rated Capacity \*\*\*\*\* 1GBJ6P1F9GV109069 1986 D136 Bus Type: (see ? for definition) Chassis Make Body Make  $\square$  A  $\square$  B ✓ C  $\Box$  D Chevrolet **Bluebird** Wheel Chair Lift Equipped? Wheel Chair Lift Equipped? ☐ Yes ✓ No ☐ Forward Facing ☐ Aisle Facing ✓ Not Applicable Type of Fuel: Is Bus: District Owned Contractor Owned If contractor owned, contractor's name is: Gas ✓ Diesel Other Revier Transportation INSPECTION TO BE FILLED OUT BY THE HIGHWAY PATROL 1st semester ✓ 2nd semester This inspection is for: Approved Approved NΑ Items listed in the Standards Items listed in the Standards Page No NA Yes No Yes Page Corr No.\* for School Buses in Montana No.\* for School Buses in Montana Belt cutter \*\*\*\* attached C17 Identification - front C34 C18 Head lamps C18 Interior lamps C18 C10 Color Ceiling - interior Turn signal lamps - front C18 C21 Seating Turn signal lamps - side (post 1987) C14 C18 Floor C18 Red amber signals - front C9 Aisle C18 Marker lamps - front C22 Tools - storage C18 Windshield C24 Windows C24 Windshield wipers C13 Warning device C20 Exterior mirrors C13 Buzzer emergency door C3 C12 Emergency door Battery C4 Generator or alternator C18 Red amber signals - rear Turn signal lamps - rear C11 C18 Service door C18 Stop lamps C6Head lamp indicator C6 C18 Marker lamps - rear Horn C20 Interior mirror C19 Strobe light - rear \*\*\* C6 Speedometer C17 Identification - rear Brakes C4 Exhaust system (no leaks) Driver seat belt Fuel tank Tires (2/32" rear - 4/32" front min.) Steering gear Fire extinguisher (5 lbs) Cleanliness C13 First aid kit C22 Stop arm No trailer hitch C13 Body fluids kit C5 C11 Defroster Required by forest regulation: C6 Heaters Shovel (securely fastened) C20 Wheelchair forward facing (post 1993) Axe (securely fastened) \*Page number reference, Standards for School Buses in Montana (2002 Edition). \*\*\*\*Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver. 
\*\*Does not apply. \*\*\*New buses ordered after 08/15/02.\*\*\*\*\*Based on original capacity listed on the manufacturers certification tag found inside the bus. On first inspection, this bus is: On reinspection, this bus is: Approved Approved Not Approved Not Approved Inspecting Patrol Officer: Inspecting Patrol Officer: Date Date Badge No.



# **MONTANA HIGHWAY PATROL**

**School Bus Inspection** School Year 2006

State	
District	
County	
Patrol	
Contractor	

TR-13 Revised 11/04

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the

	ay Patrol as soon as all defects are correct	eu.											
Instructions to OPI from School District:													
This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.  Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.													
	County # and County Name	JIACK OC	it the er	101, 01	Tillay III	District Name							
45 Sanders						Pla	ains Publi	ic Scho	ols				
Vehic	le I.D. # (VIN) - Entire Number		Mo	del Ye	ar	Licen			Rated C		*****		
	1GBJ6P1B6GV104750			198	6		E36				60		
Chas	sis Make				Body Mal	(e		Bus Type:	(see ? fo	r defin			
	Chevrolet						omas	$\Box$ A $\Box$	•	Z C	D		
Whee	Chair Lift Equipped?	Whe	el Chai	r Lift Ed	quipped?		Jilias						
☐ Ye	_ `		orwar				e Facing 🗹 N	ot Applica	hla				
	of Fuel:						ontractor Owned If co			ractor's	name	is.	
		13 0		Distric	owned	• •			rica, cont	ractor s	Tiarric	io.	
<b>✓</b> G	as 🗌 Diesel 🗌 Other						Revier Transp	ortation					
						CTION							
	Thio					THE HIGH	GHWAY PATROL ter ✓ 2nd seme	otor					
	Triis	inspect		roved	18	t semes	ter 💌 zna seme	ster			App	roved	
Page	Items listed in the Standards	Yes	No	NA	Corr	Page	Items listed in			Yes	No	NA	Corr
No.*	for School Buses in Montana			**		No.*	for School Bus		na			**	
C17	Identification - front				<del> </del>		Belt cutter **** attach	ied					
C18 C10	Head lamps Color				+	C18	Interior lamps Ceiling - interior					-	
C18	Turn signal lamps - front				+	C21	Seating						
C18	Turn signal lamps - side (post 1987)				+	C14 Floor							
C18	Red amber signals - front					C9 Aisle							
C18	Marker lamps - front					C22							
C18	Windshield					C24 Windows							
C24	Windshield wipers					C13	Warning device						
C20	Exterior mirrors				1	C13	Buzzer emergency d	oor					
C3	Battery					C12	Emergency door						
C4	Generator or alternator					C18	Red amber signals -	rear					
C11	Service door					C18	Turn signal lamps - re	ear					
C6	Head lamp indicator					C18	Stop lamps						
C6	Horn						Marker lamps - rear						
C20	Interior mirror						Strobe light - rear ***						
C6	Speedometer						Identification - rear						
C2	Brakes					C4	Exhaust system (no l	eaks)					
C21	Driver seat belt				<del> </del>	C5	Fuel tank	011 (11	`			<u> </u>	
C7 C13	Steering gear Fire extinguisher (5 lbs)				-	C7	Tires (2/32" rear - 4/3 Cleanliness	32" front min	.)				
C13	First aid kit	1			+	C22	Stop arm					1	
C13	Body fluids kit				+	C5	No trailer hitch						
C11	Defroster Defroster				+	03	Required by forest	equiation:					
C6	Heaters				+		Shovel (securely fast	_				1	
C20	Wheelchair forward facing (post 1993)				+		Axe (securely fastene						
*Page ni	umber reference, Standards for School Buses in N						equired to wear lap/shoul	der belts - cutt		d nearby	driver.	_1	
	ot apply. ***New buses ordered after 08/15/02.**	Based	on origir	іаі сара	city listed			_	ie the bus.				
On fi	st inspection, this bus is:					On re	inspection, this bus	is:					
	Approved						Approved						
	Not Approved						Not Approved						
Insped	ting Patrol Officer:					Inspec	cting Patrol Officer:						
Badge	No.	Date				Badge No Date							
Signa	rure of District Official					Date							



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Holona, MT 59620-2501

## **MONTANA HIGHWAY PATROL**

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

Helena, MT 59620-2501 This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected. Instructions to OPI from School District: ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records. Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction. OPI County # and County Name District Name **Plains Public Schools** 45 Sanders Vehicle I.D. # (VIN) - Entire Number Model Year License # Rated Capacity \*\*\*\*\* 4CDT78R15R2700745 1994 D135 Bus Type: (see ? for definition) Chassis Make Body Make  $\Box$  A  $\Box$  B  $\Box$  C **✓** D Other **Thomas** Wheel Chair Lift Equipped? Wheel Chair Lift Equipped? ☐ Yes ✓ No ☐ Forward Facing ☐ Aisle Facing ✓ Not Applicable Type of Fuel: Is Bus: District Owned Contractor Owned If contractor owned, contractor's name is: Gas ✓ Diesel Other Revier Transportation INSPECTION TO BE FILLED OUT BY THE HIGHWAY PATROL 1st semester ✓ 2nd semester This inspection is for: Approved Approved Page NΑ Items listed in the Standards Items listed in the Standards No NA Yes No Yes Page Corr No.\* for School Buses in Montana No.\* for School Buses in Montana Belt cutter \*\*\*\* attached C17 Identification - front C34 C18 Head lamps C18 Interior lamps C18 C10 Color Ceiling - interior Turn signal lamps - front C18 C21 Seating Turn signal lamps - side (post 1987) C14 C18 Floor C18 Red amber signals - front C9 Aisle C18 Marker lamps - front C22 Tools - storage C18 Windshield C24 Windows C24 Windshield wipers C13 Warning device C20 Exterior mirrors C13 Buzzer emergency door C3 C12 Emergency door Battery C4 Generator or alternator C18 Red amber signals - rear Turn signal lamps - rear C11 C18 Service door C18 Stop lamps C6Head lamp indicator C6 C18 Marker lamps - rear Horn C20 Interior mirror C19 Strobe light - rear \*\*\* C6 Speedometer C17 Identification - rear Brakes C4 Exhaust system (no leaks) Driver seat belt Fuel tank Tires (2/32" rear - 4/32" front min.) Steering gear Fire extinguisher (5 lbs) Cleanliness C13 First aid kit C22 Stop arm No trailer hitch C13 Body fluids kit C5 C11 Defroster Required by forest regulation: C6 Heaters Shovel (securely fastened) C20 Wheelchair forward facing (post 1993) Axe (securely fastened) \*Page number reference, Standards for School Buses in Montana (2002 Edition). \*\*\*\*Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver. 
\*\*Does not apply. \*\*\*New buses ordered after 08/15/02.\*\*\*\*\*Based on original capacity listed on the manufacturers certification tag found inside the bus. On first inspection, this bus is: On reinspection, this bus is: Approved Approved Not Approved Not Approved Inspecting Patrol Officer: Inspecting Patrol Officer: Date Date Badge No.



# **MONTANA HIGHWAY PATROL**

**School Bus Inspection** School Year 2006

State	
District	
County	
Patrol	
Contractor	

TR-13 Revised 11/04

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the

Highway Patrol as soon as all defects are corrected.														
Instructions to OPI from School District:														
☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.														
Please make corrections noted below. Don't black out the error, OPI may no							need to read it to make the correction.							
OPI County # and County Name					District Name									
	45 Sanders							<u>ains Public S</u>						
Vehic	le I.D. # (VIN) - Entire Number		Mo	del Ye	ear	Licen	se #	Rat	ed Capacity	/ ****				
	1GBL6P1G1KV101039			198	89		E32			60				
Chas	sis Make				Body Mal	ke	LUZ	Bus Type: (see	? for defin		-			
					,									
	Chevrolet						omas	$\Box$ A $\Box$ B	✓ C	□D				
Whee	el Chair Lift Equipped?	Whe	el Chai	r Lift E	quipped	•								
☐ Ye	es 🗹 No	□ F	orwar	d Fa	cing	Aisle	e Facing 🗹 N	ot Applicable						
Type	of Fuel:	Is B	us:	Distri			ontractor Owned If co		contractor's	name	is:			
□G	as 🗹 Diesel 🗌 Other						Revier Transp	ortation						
					INSPE	CTION								
					OUT BY	THE HI	GHWAY PATROL							
	This	inspect	ion is fo	r:	1s	t semes	ter 2nd seme	ster						
		T		roved	1.						oroved			
Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in for School Bus		Yes	No	NA **	Corr		
C17	Identification - front					C34	Belt cutter **** attach			+				
C18	Head lamps					C18	Interior lamps	eu		+	+			
C10	Color					C18	Ceiling - interior			+	+			
C18	Turn signal lamps - front					C21	Seating			+	+			
C18	Turn signal lamps - side (post 1987)					C14	Floor			†	1			
C18	Red amber signals - front			C9 Aisle				†	1					
C18	Marker lamps - front					C22 Tools - storage								
C18	Windshield					C24	Windows							
C24	Windshield wipers					C13	Warning device			<u> </u>				
C20	Exterior mirrors					C13	Buzzer emergency de	oor						
C3	Battery					C12	Emergency door			┼──				
C4 C11	Generator or alternator Service door					C18	Red amber signals - Turn signal lamps - re			+	+-	+		
C6	Head lamp indicator					C18	Stop lamps	zai		+	+			
C6	Horn					C18	Marker lamps - rear			+	+	+		
C20	Interior mirror					C19	Strobe light - rear ***			+	+			
C6	Speedometer					C17	Identification - rear			†	1			
C2	Brakes					C4	Exhaust system (no l	eaks)						
C21	Driver seat belt					C5	Fuel tank							
C7	Steering gear					C7	Tires (2/32" rear - 4/3	32" front min.)		<u> </u>				
C13	Fire extinguisher (5 lbs)					000	Cleanliness			<u> </u>				
C13	First aid kit					C22	Stop arm			<del> </del>	+	-		
C13	Body fluids kit  Defroster					C5	No trailer hitch	e audation :		₩				
C11 C6	Heaters			1			Required by forest r Shovel (securely fast			+	+			
C20	Wheelchair forward facing (post 1993)						Axe (securely fastene	,		+	+			
	umber reference, Standards for School Buses in N	Montana (	(2002 Ed	ition). '	****Bus dri	vers are r			ached nearby	driver.				
	not apply. ***New buses ordered after 08/15/02.**													
On fi	st inspection, this bus is:					On re	einspection, this bus	is:						
	Approved						Approved							
	Not Approved						Not Approved							
Insped	cting Patrol Officer:					Inspec	cting Patrol Officer:							
Badge		Date					e No		Date					
Signature of District Official					Date									



Date

Signature of District Official

## **MONTANA HIGHWAY PATROL**

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

School Year 2006 Helena, MT 59620-2501 This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected. Instructions to OPI from School District: ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records. Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction. OPI County # and County Name District Name **Plains Public Schools** 45 Sanders Vehicle I.D. # (VIN) - Entire Number Model Year License # Rated Capacity \*\*\*\*\* 1T7A3188XL1103116 1990 **E29** Bus Type: (see ? for definition) Chassis Make Body Make  $\Box$  A  $\Box$  B  $\Box$  C **✓** D **Thomas Thomas** Wheel Chair Lift Equipped? Wheel Chair Lift Equipped? ☐ Yes ✓ No ☐ Forward Facing ☐ Aisle Facing ✓ Not Applicable Type of Fuel: Is Bus: District Owned Contractor Owned If contractor owned, contractor's name is: Gas ✓ Diesel Other Revier Transportation INSPECTION TO BE FILLED OUT BY THE HIGHWAY PATROL 1st semester ✓ 2nd semester This inspection is for: Approved Approved NΑ Items listed in the Standards Items listed in the Standards Page No NA Yes No Yes Page Corr No.\* for School Buses in Montana No.\* for School Buses in Montana Belt cutter \*\*\*\* attached C17 Identification - front C34 C18 Head lamps C18 Interior lamps C18 Ceiling - interior C10 Color Turn signal lamps - front C18 C21 Seating Turn signal lamps - side (post 1987) C14 C18 Floor C18 Red amber signals - front C9 Aisle C18 Marker lamps - front C22 Tools - storage C18 Windshield C24 Windows C24 Windshield wipers C13 Warning device C20 Exterior mirrors C13 Buzzer emergency door C3 C12 Emergency door Battery C4 Generator or alternator C18 Red amber signals - rear Turn signal lamps - rear C11 C18 Service door C18 Stop lamps C6Head lamp indicator C6 C18 Marker lamps - rear Horn C20 Interior mirror C19 Strobe light - rear \*\*\* C6 Speedometer C17 Identification - rear Brakes C4 Exhaust system (no leaks) Driver seat belt Fuel tank Tires (2/32" rear - 4/32" front min.) Steering gear Fire extinguisher (5 lbs) Cleanliness C13 First aid kit C22 Stop arm No trailer hitch C13 Body fluids kit C5 C11 Defroster Required by forest regulation: C6 Heaters Shovel (securely fastened) C20 Wheelchair forward facing (post 1993) Axe (securely fastened) \*Page number reference, Standards for School Buses in Montana (2002 Edition). \*\*\*\*Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver. 
\*\*Does not apply. \*\*\*New buses ordered after 08/15/02.\*\*\*\*\*Based on original capacity listed on the manufacturers certification tag found inside the bus. On first inspection, this bus is: On reinspection, this bus is: Approved Approved Not Approved Not Approved Inspecting Patrol Officer: Inspecting Patrol Officer:

Badge No.

Date

TR-13 Revised 11/04



Linda McCulloch, Superintendent Office of Public Instruction PO Box 202501

## MONTANA HIGHWAY PATROL

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

Helena, MT 59620-2501 This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected. Instructions to OPI from School District: ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records. Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction. OPI County # and County Name District Name **Thompson Falls Pub Schls** 45 Sanders Vehicle I.D. # (VIN) - Entire Number Model Year Rated Capacity \*\*\*\*\* License # 1BAAGCSH9LF034180 1990 J450 Bus Type: (see ? for definition) Chassis Make Body Make  $\Box$  A  $\Box$  B  $\Box$  C **✓** D **Bluebird Bluebird** Wheel Chair Lift Equipped? Wheel Chair Lift Equipped? ☐ Yes ✓ No ☐ Forward Facing ☐ Aisle Facing ✓ Not Applicable Type of Fuel: Is Bus: District Owned Contractor Owned If contractor owned, contractor's name is: Gas ✓ Diesel Other Mosher Transportation INSPECTION TO BE FILLED OUT BY THE HIGHWAY PATROL 1st semester ✓ 2nd semester This inspection is for: Approved Approved NΑ Items listed in the Standards Items listed in the Standards Page No NA Yes No Yes Page Corr No.\* for School Buses in Montana No.\* for School Buses in Montana Belt cutter \*\*\*\* attached C17 Identification - front C34 C18 Head lamps C18 Interior lamps C18 Ceiling - interior C10 Color Turn signal lamps - front C18 C21 Seating Turn signal lamps - side (post 1987) C14 C18 Floor C18 Red amber signals - front C9 Aisle C18 Marker lamps - front C22 Tools - storage C18 Windshield C24 Windows C24 Windshield wipers C13 Warning device C20 Exterior mirrors C13 Buzzer emergency door C3 C12 Emergency door Battery C4 Generator or alternator C18 Red amber signals - rear Turn signal lamps - rear C11 C18 Service door C18 Stop lamps C6Head lamp indicator C6 C18 Marker lamps - rear Horn C20 Interior mirror C19 Strobe light - rear \*\*\* C6 Speedometer C17 Identification - rear Brakes C4 Exhaust system (no leaks) Driver seat belt Fuel tank Tires (2/32" rear - 4/32" front min.) Steering gear Fire extinguisher (5 lbs) Cleanliness C13 First aid kit C22 Stop arm No trailer hitch C13 Body fluids kit C5 C11 Defroster Required by forest regulation: C6 Heaters Shovel (securely fastened) C20 Wheelchair forward facing (post 1993) Axe (securely fastened) \*Page number reference, Standards for School Buses in Montana (2002 Edition). \*\*\*\*Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver. 
\*\*Does not apply. \*\*\*New buses ordered after 08/15/02.\*\*\*\*\*Based on original capacity listed on the manufacturers certification tag found inside the bus. On first inspection, this bus is: On reinspection, this bus is: Approved Approved Not Approved Not Approved Inspecting Patrol Officer: Inspecting Patrol Officer: Date Date

Badge No.



#### MONTANA HIGHWAY PATROL

**School Bus Inspection** School Year 2006

State	
District	
County	
Patrol	
Contractor	

TR-13 Revised 11/04

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected. Instructions to OPI from School District:

☐ This bus has been sold, retired, or is no longer☐ Please make corrections noted below. Don't be				rection.	
OPI County # and County Name		District Name			
45 Sanders			Thor	npson Fa	alls Pub Schis
Vehicle I.D. # (VIN) - Entire Number	Mode	l Year	License #		Rated Capacity *****
1T88P3B16T1142694	1994		J716		72
Chassis Make		Body Ma	ake	Bus Type	e: (see ? for definition)
Thomas	Thomas □ A □ B □ C ☑ D				$\square$ B $\square$ C $\checkmark$ D
Wheel Chair Lift Equipped?	Wheel Chair Lit	ft Equipped	?		
☐ Yes ✓ No	☐ Forward Facing ☐ Aisle Facing ☑ Not Applicable				
Type of Fuel:	Is Bus: ☐ District Owned ✔ Contractor Owned If contractor owned, contractor's name is:				
☐ Gas ☑ Diesel ☐ Other	Mosher Transportation				
INSPECTION					
	TO RE FILLE	FD OUT BY	/ THE HIGHWAY PATROI		

\_\_\_ 1st semester ✓ 2nd semester This inspection is for:

Approved Approved Page NΑ Items listed in the Standards Yes NA Page Items listed in the Standards No Yes Nο Corr Corr No.\* for School Buses in Montana No.\* for School Buses in Montana Belt cutter \*\*\*\* attached C17 Identification - front C34 C18 Head lamps C18 Interior lamps C10 C18 Color Ceiling - interior Turn signal lamps - front C18 C21 Seating Turn signal lamps - side (post 1987) C14 C18 Floor C18 Red amber signals - front C9 Aisle C18 Marker lamps - front C22 Tools - storage C18 Windshield C24 Windows C24 Windshield wipers C13 Warning device C20 Exterior mirrors C13 Buzzer emergency door C3 C12 Emergency door Battery C4 Generator or alternator C18 Red amber signals - rear Turn signal lamps - rear C11 C18 Service door C6 C18 Head lamp indicator Stop lamps C18 C6 Marker lamps - rear Horn C20 C19 Strobe light - rear \*\*\* Interior mirror C6 Speedometer C17 Identification - rear Brakes C4 Exhaust system (no leaks) Driver seat belt C5 Fuel tank Steering gear Tires (2/32" rear - 4/32" front min.) Fire extinguisher (5 lbs) Cleanliness C13 First aid kit C22 Stop arm C13 Body fluids kit C5 No trailer hitch C11 Defroster Required by forest regulation: C6 Heaters Shovel (securely fastened) C20 Wheelchair forward facing (post 1993) Axe (securely fastened)

\*Page number reference, Standards for School Buses in Montana (2002 Edition). \*\*\*\*Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver. 
\*\*Does not apply. \*\*\*New buses ordered after 08/15/02.\*\*\*\*\*Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:	n, this bus is:  On reinspection, this bus is:			
Approved		Approved		
Not Approved	Not Approved			
Inspecting Patrol Officer:		Inspecting Patrol Officer:		
Badge No Date		Badge No.	Date	
Signature of District Official		Date		



# **MONTANA HIGHWAY PATROL**

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

TR-13 Revised 11/04

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Highway Patrol as soon as all defects are corrected.												
Instructions to OPI from School District:												
This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.												
Please make corrections noted below. Don't black out the error, OPI may ne												
OPI County # and County Name			Distri	ct Name								
										_		
	45 Sanders							npson Falls				
Vehic	le I.D. # (VIN) - Entire Number		Mo	odel Ye	ar	Licen	se#	R	ated Capac	ity *****		
	1GBM6P1G6EV109582			198	4		E101		65			
Chas	sis Make				Body Mal	ке		Bus Type: (s	ee ? for def			
					,							
	Chevrolet						omas		ь 🖭 С			
whee	el Chair Lift Equipped?	Whe	el Chai	r Lift E	quipped?	,						
□ Ye	es 🗹 No	□ F	orwar	d Fac	ing	☐ Aisl	e Facing 🛮 🗹 N	ot Applicable	е			
Туре	of Fuel:	Is B	us:	Distric	t Owned	/ C	ontractor Owned If co	ontractor owned	d, contracto	r's name	is:	
□G	as ☑ Diesel ☐ Other											
	as 🛂 Diesei 🗆 Othei						Mosher Trans	portation				
					INSPE	CTION						
							GHWAY PATROL					
	This	inspect			1s	t semes	ter 2nd seme	ster				
	1. 1	1.7		roved	10		1, 0		1.,		proved	
Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in for School Bus		Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attach				+-	
C18	Head lamps				+	C18	Interior lamps				+	+
C10	Color					C18	Ceiling - interior				+	
C18	Turn signal lamps - front					C21	Seating				1	
C18	Turn signal lamps - side (post 1987)					C14	Floor					
C18	Red amber signals - front					C9	Aisle					
C18	Marker lamps - front					C22	Tools - storage					
C18	Windshield					C24 Windows						
C24	Windshield wipers					C13 Warning device						
C20	Exterior mirrors				+	C13	Buzzer emergency de	oor			+	
C3 C4	Battery Generator or alternator				+	C12 Emergency door C18 Red amber signals - rear						
C11	Service door				+	C18 Turn signal lamps - rear						
C6	Head lamp indicator					C18 Stop lamps						
C6	Horn					C18	Marker lamps - rear					
C20	Interior mirror					C19	Strobe light - rear ***					
C6	Speedometer					C17	Identification - rear					
C2	Brakes					C4	Exhaust system (no l	eaks)				
C21	Driver seat belt					C5	Fuel tank				<del></del>	
C7	Steering gear					C7	Tires (2/32" rear - 4/3	32" front min.)			+	
C13	Fire extinguisher (5 lbs) First aid kit				+	C22	Cleanliness Stop arm				+-	
C13	Body fluids kit					C5	No trailer hitch				+	
C11	Defroster					00	Required by forest i	egulation:			+	
C6	Heaters						Shovel (securely fast					
C20	Wheelchair forward facing (post 1993)						Axe (securely fastene	ed)			1	
	umber reference, Standards for School Buses in output apply. ***New buses ordered after 08/15/02.**									by driver.		
On fi	st inspection, this bus is:					On re	inspection, this bus	is:				
<u> </u>				Approved								
☐ Not Approved					Not Approved							
Inspecting Patrol Officer:				cting Patrol Officer:								
Badge No Date Badge No  Signature of District Official Date				: NU.		Date						
Signa	uie oi District Official					Date						



## **MONTANA HIGHWAY PATROL**

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

Helena, MT 59620-2501 This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected. Instructions to OPI from School District: ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records. Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction. OPI County # and County Name District Name **Thompson Falls Pub Schls** 45 Sanders Vehicle I.D. # (VIN) - Entire Number Model Year Rated Capacity \*\*\*\*\* License # 1BAAGCPH32F202970 2002 E104 Bus Type: (see ? for definition) Chassis Make Body Make  $\square$  A  $\square$  B ✓ C  $\Box$  D **Bluebird Bluebird** Wheel Chair Lift Equipped? Wheel Chair Lift Equipped? ☐ Yes ✓ No ☐ Forward Facing ☐ Aisle Facing ✓ Not Applicable Type of Fuel: Is Bus: District Owned Contractor Owned If contractor owned, contractor's name is: Gas ✓ Diesel Other Mosher Transportation INSPECTION TO BE FILLED OUT BY THE HIGHWAY PATROL 1st semester ✓ 2nd semester This inspection is for: Approved Approved NΑ Items listed in the Standards Items listed in the Standards Page No NA Yes No Yes Page Corr No.\* for School Buses in Montana No.\* for School Buses in Montana Belt cutter \*\*\*\* attached C17 Identification - front C34 C18 Head lamps C18 Interior lamps C18 C10 Color Ceiling - interior Turn signal lamps - front C18 C21 Seating Turn signal lamps - side (post 1987) C14 C18 Floor C18 Red amber signals - front C9 Aisle C18 Marker lamps - front C22 Tools - storage C18 Windshield C24 Windows C24 Windshield wipers C13 Warning device C20 Exterior mirrors C13 Buzzer emergency door C3 C12 Emergency door **Battery** C4 Generator or alternator C18 Red amber signals - rear Turn signal lamps - rear C11 C18 Service door C18 Stop lamps C6Head lamp indicator C6 C18 Marker lamps - rear Horn C20 Interior mirror C19 Strobe light - rear \*\*\* C6 Speedometer C17 Identification - rear Brakes C4 Exhaust system (no leaks) Driver seat belt Fuel tank Tires (2/32" rear - 4/32" front min.) Steering gear Fire extinguisher (5 lbs) Cleanliness C13 First aid kit C22 Stop arm No trailer hitch C13 Body fluids kit C5 C11 Defroster Required by forest regulation: C6 Heaters Shovel (securely fastened)

\*Page number reference, Standards for School Buses in Montana (2002 Edition). \*\*\*\*Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver. 
\*\*Does not apply. \*\*\*New buses ordered after 08/15/02.\*\*\*\*\*Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

Approved
Not Approved
Not Approved
Inspecting Patrol Officer:

Badge No.

Date

On reinspection, this bus is:
Approved
Inspection Patrol Officer:

Badge No.
Date

Date

Signature of District Official

Wheelchair forward facing (post 1993)

C20

Date

Axe (securely fastened)

TR-13 Revised 11/04



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Holona, MT 59620-2501

## **MONTANA HIGHWAY PATROL**

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

TR-13 Revised 11/04

Helena, MT 59620-2501 This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected. Instructions to OPI from School District: ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records. Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction. OPI County # and County Name District Name **Thompson Falls Pub Schls** 45 Sanders Vehicle I.D. # (VIN) - Entire Number Model Year Rated Capacity \*\*\*\*\* License # **1BAAACSH5PF054719** 1993 E117 Bus Type: (see ? for definition) Chassis Make Body Make  $\Box$  A  $\Box$  B  $\Box$  C **✓** D **Bluebird Bluebird** Wheel Chair Lift Equipped? Wheel Chair Lift Equipped? ☐ Yes ✓ No ☐ Forward Facing ☐ Aisle Facing ✓ Not Applicable Type of Fuel: Is Bus: District Owned Contractor Owned If contractor owned, contractor's name is: Gas ✓ Diesel Other Mosher Transportation INSPECTION TO BE FILLED OUT BY THE HIGHWAY PATROL 1st semester ✓ 2nd semester This inspection is for: Approved Approved NΑ Items listed in the Standards Items listed in the Standards Page No NA Yes No Yes Page Corr No.\* for School Buses in Montana No.\* for School Buses in Montana Belt cutter \*\*\*\* attached C17 Identification - front C34 C18 Head lamps C18 Interior lamps C18 C10 Color Ceiling - interior Turn signal lamps - front C18 C21 Seating Turn signal lamps - side (post 1987) C14 C18 Floor C18 Red amber signals - front C9 Aisle C18 Marker lamps - front C22 Tools - storage C18 Windshield C24 Windows C24 Windshield wipers C13 Warning device C20 Exterior mirrors C13 Buzzer emergency door C3 C12 Emergency door **Battery** C4 Generator or alternator C18 Red amber signals - rear Turn signal lamps - rear C11 C18 Service door C18 Stop lamps C6Head lamp indicator C6 C18 Marker lamps - rear Horn C20 Interior mirror C19 Strobe light - rear \*\*\* C6 Speedometer C17 Identification - rear Brakes C4 Exhaust system (no leaks) Driver seat belt Fuel tank Tires (2/32" rear - 4/32" front min.) Steering gear Fire extinguisher (5 lbs) Cleanliness C13 First aid kit C22 Stop arm No trailer hitch C13 Body fluids kit C5 C11 Defroster Required by forest regulation: C6 Heaters Shovel (securely fastened) C20 Wheelchair forward facing (post 1993) Axe (securely fastened) \*Page number reference, Standards for School Buses in Montana (2002 Edition). \*\*\*\*Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver. 
\*\*Does not apply. \*\*\*New buses ordered after 08/15/02.\*\*\*\*\*Based on original capacity listed on the manufacturers certification tag found inside the bus. On first inspection, this bus is: On reinspection, this bus is: Approved Approved Not Approved Not Approved Inspecting Patrol Officer: Inspecting Patrol Officer: Date Date Badge No.



## **MONTANA HIGHWAY PATROL**

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

TR-13 Revised 11/04

Helena, MT 59620-2501 This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected. Instructions to OPI from School District: ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records. Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction. OPI County # and County Name District Name **Thompson Falls Pub Schls** 45 Sanders Vehicle I.D. # (VIN) - Entire Number Model Year Rated Capacity \*\*\*\*\* License # **1BAAHCSH5LF035520** 1990 E103 Bus Type: (see ? for definition) Chassis Make Body Make  $\Box$  A  $\Box$  B  $\Box$  C **✓** D **Bluebird Bluebird** Wheel Chair Lift Equipped? Wheel Chair Lift Equipped? ☐ Yes ✓ No ☐ Forward Facing ☐ Aisle Facing ✓ Not Applicable Type of Fuel: Is Bus: District Owned Contractor Owned If contractor owned, contractor's name is: Gas ✓ Diesel Other Mosher Transportation INSPECTION TO BE FILLED OUT BY THE HIGHWAY PATROL 1st semester ✓ 2nd semester This inspection is for: Approved Approved NΑ Items listed in the Standards Items listed in the Standards Page No NA Yes No Yes Page Corr No.\* for School Buses in Montana No.\* for School Buses in Montana Belt cutter \*\*\*\* attached C17 Identification - front C34 C18 Head lamps C18 Interior lamps C18 C10 Color Ceiling - interior Turn signal lamps - front C18 C21 Seating Turn signal lamps - side (post 1987) C14 C18 Floor C18 Red amber signals - front C9 Aisle C18 Marker lamps - front C22 Tools - storage C18 Windshield C24 Windows C24 Windshield wipers C13 Warning device C20 Exterior mirrors C13 Buzzer emergency door C3 C12 Emergency door **Battery** C4 Generator or alternator C18 Red amber signals - rear Turn signal lamps - rear C11 C18 Service door C18 Stop lamps C6Head lamp indicator C6 C18 Marker lamps - rear Horn C20 Interior mirror C19 Strobe light - rear \*\*\* C6 Speedometer C17 Identification - rear Brakes C4 Exhaust system (no leaks) Driver seat belt Fuel tank Tires (2/32" rear - 4/32" front min.) Steering gear Fire extinguisher (5 lbs) Cleanliness C13 First aid kit C22 Stop arm No trailer hitch C13 Body fluids kit C5 C11 Defroster Required by forest regulation: C6 Heaters Shovel (securely fastened) C20 Wheelchair forward facing (post 1993) Axe (securely fastened) \*Page number reference, Standards for School Buses in Montana (2002 Edition). \*\*\*\*Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver. 
\*\*Does not apply. \*\*\*New buses ordered after 08/15/02.\*\*\*\*\*Based on original capacity listed on the manufacturers certification tag found inside the bus. On first inspection, this bus is: On reinspection, this bus is:

\*Does not apply. \*\*\*New buses ordered after 08/15/02.\*\*\*\*\*Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

Approved
Not Approved
Not Approved
Inspecting Patrol Officer:

Badge No.

Date

Badge No.

Date

Date

Date



Date

Signature of District Official

## **MONTANA HIGHWAY PATROL**

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

Helena, MT 59620-2501 This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected. Instructions to OPI from School District: This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records. Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction. OPI County # and County Name District Name **Thompson Falls Pub Schls** 45 Sanders Vehicle I.D. # (VIN) - Entire Number Model Year Rated Capacity \*\*\*\*\* License # 1FDNB70K2FVA46625 1985 E102 Bus Type: (see ? for definition) Chassis Make Body Make  $\Box$  A  $\Box$  B ✓ C  $\Box$  D **Bluebird** Ford Wheel Chair Lift Equipped? Wheel Chair Lift Equipped? ☐ Yes ✓ No ☐ Forward Facing ☐ Aisle Facing ✓ Not Applicable Type of Fuel: Is Bus: District Owned Contractor Owned If contractor owned, contractor's name is: ✓ Gas Diesel Other John Mosher INSPECTION TO BE FILLED OUT BY THE HIGHWAY PATROL 1st semester This inspection is for: Approved Approved Page NΑ Items listed in the Standards Items listed in the Standards No NA Yes No Yes Corr Page Corr No.\* for School Buses in Montana No.\* for School Buses in Montana Belt cutter \*\*\*\* attached C17 Identification - front C34 C18 Head lamps C18 Interior lamps C18 Ceiling - interior C10 Color Turn signal lamps - front C18 C21 Seating Turn signal lamps - side (post 1987) C14 C18 Floor C18 Red amber signals - front C9 Aisle C18 Marker lamps - front C22 Tools - storage C18 Windshield C24 Windows C24 Windshield wipers C13 Warning device C20 Exterior mirrors C13 Buzzer emergency door C3 C12 Emergency door **Battery** C4 Generator or alternator C18 Red amber signals - rear Turn signal lamps - rear C11 C18 Service door C18 Stop lamps C6Head lamp indicator C6 C18 Marker lamps - rear Horn C20 Interior mirror C19 Strobe light - rear \*\*\* C6 Speedometer C17 Identification - rear Brakes C4 Exhaust system (no leaks) Driver seat belt Fuel tank Tires (2/32" rear - 4/32" front min.) Steering gear Fire extinguisher (5 lbs) Cleanliness C13 First aid kit C22 Stop arm No trailer hitch C13 Body fluids kit C5 C11 Defroster Required by forest regulation: C6 Heaters Shovel (securely fastened) C20 Wheelchair forward facing (post 1993) Axe (securely fastened) \*Page number reference, Standards for School Buses in Montana (2002 Edition). \*\*\*\*Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver. 
\*\*Does not apply. \*\*\*New buses ordered after 08/15/02.\*\*\*\*\*Based on original capacity listed on the manufacturers certification tag found inside the bus. On first inspection, this bus is: On reinspection, this bus is: Approved Approved Not Approved Not Approved Inspecting Patrol Officer: Inspecting Patrol Officer:

Badge No.

Date



Not Approved

Inspecting Patrol Officer:

Signature of District Official

Date

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Holona, MT 59620-2501

## **MONTANA HIGHWAY PATROL**

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

Helena, MT 59620-2501 This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected. Instructions to OPI from School District: This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records. Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction. OPI County # and County Name District Name **Thompson Falls Pub Schls** 45 Sanders Vehicle I.D. # (VIN) - Entire Number Model Year Rated Capacity \*\*\*\*\* License # 1HVLPUGN1HH469087 1987 E109 Bus Type: (see ? for definition) Chassis Make Body Make  $\Box$  A  $\Box$  B ✓ C  $\Box$  D International **Thomas** Wheel Chair Lift Equipped? Wheel Chair Lift Equipped? ✓ Yes ☐ No ✓ Forward Facing ☐ Aisle Facing ☐ Not Applicable Type of Fuel: Is Bus: District Owned Contractor Owned If contractor owned, contractor's name is: Gas ✓ Diesel Other Mosher Transportation INSPECTION TO BE FILLED OUT BY THE HIGHWAY PATROL 1st semester ✓ 2nd semester This inspection is for: Approved Approved NΑ Items listed in the Standards Items listed in the Standards Page No NA Page Yes No Yes Corr No.\* for School Buses in Montana No.\* for School Buses in Montana Belt cutter \*\*\*\* attached C17 Identification - front C34 C18 Head lamps C18 Interior lamps C18 Ceiling - interior C10 Color Turn signal lamps - front C18 C21 Seating Turn signal lamps - side (post 1987) C14 C18 Floor C18 Red amber signals - front C9 Aisle C18 Marker lamps - front C22 Tools - storage C18 Windshield C24 Windows C24 Windshield wipers C13 Warning device C20 Exterior mirrors C13 Buzzer emergency door C3 C12 Emergency door **Battery** C4 Generator or alternator C18 Red amber signals - rear Turn signal lamps - rear C11 C18 Service door C18 Stop lamps C6Head lamp indicator C6 C18 Marker lamps - rear Horn C20 Interior mirror C19 Strobe light - rear \*\*\* C6 Speedometer C17 Identification - rear Brakes C4 Exhaust system (no leaks) Driver seat belt Fuel tank Tires (2/32" rear - 4/32" front min.) Steering gear Fire extinguisher (5 lbs) Cleanliness C13 First aid kit C22 Stop arm No trailer hitch C13 Body fluids kit C5 C11 Defroster Required by forest regulation: C6 Heaters Shovel (securely fastened) C20 Wheelchair forward facing (post 1993) Axe (securely fastened) \*Page number reference, Standards for School Buses in Montana (2002 Edition). \*\*\*\*Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver. 
\*\*Does not apply. \*\*\*New buses ordered after 08/15/02.\*\*\*\*\*Based on original capacity listed on the manufacturers certification tag found inside the bus. On first inspection, this bus is: On reinspection, this bus is: Approved Approved

Not Approved

Badge No.

Date

Inspecting Patrol Officer:

TR-13 Revised 11/04



Linda McCulloch, Superintendent Office of Public Instruction PO Box 202501 Helena MT 59620-2501

#### **MONTANA HIGHWAY PATROL**

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

TR-13 Revised 11/04

Helena, MT 59620-2501 This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected. Instructions to OPI from School District: This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records. Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction. OPI County # and County Name District Name **Thompson Falls Pub Schls** 45 Sanders Vehicle I.D. # (VIN) - Entire Number Model Year Rated Capacity \*\*\*\*\* License # 4UZGCJBA0YCG82772 2000 E114 Bus Type: (see ? for definition) Chassis Make Body Make  $\Box$  A  $\Box$  B ✓ C  $\Box$  D Freightliner **Thomas** Wheel Chair Lift Equipped? Wheel Chair Lift Equipped? ☐ Yes ✓ No ☐ Forward Facing ☐ Aisle Facing ✓ Not Applicable Type of Fuel: Is Bus: District Owned Contractor Owned If contractor owned, contractor's name is: Gas ✓ Diesel Other Revier Transportation INSPECTION TO BE FILLED OUT BY THE HIGHWAY PATROL 1st semester ✓ 2nd semester This inspection is for: Approved Approved NΑ Items listed in the Standards Items listed in the Standards Page No NA Yes No Yes Page Corr No.\* for School Buses in Montana No.\* for School Buses in Montana Belt cutter \*\*\*\* attached C17 Identification - front C34 C18 Head lamps C18 Interior lamps C18 Ceiling - interior C10 Color Turn signal lamps - front C18 C21 Seating Turn signal lamps - side (post 1987) C14 C18 Floor C18 Red amber signals - front C9 Aisle C18 Marker lamps - front C22 Tools - storage C18 Windshield C24 Windows C24 Windshield wipers C13 Warning device C20 Exterior mirrors C13 Buzzer emergency door C3 C12 Emergency door **Battery** C4 Generator or alternator C18 Red amber signals - rear Turn signal lamps - rear C11 C18 Service door Head lamp indicator C18 Stop lamps C6C6 C18 Marker lamps - rear Horn C20 Interior mirror C19 Strobe light - rear \*\*\* C6 Speedometer C17 Identification - rear Brakes C4 Exhaust system (no leaks) Driver seat belt Fuel tank Tires (2/32" rear - 4/32" front min.) Steering gear Fire extinguisher (5 lbs) Cleanliness C13 First aid kit C22 Stop arm No trailer hitch C13 Body fluids kit C5 C11 Defroster Required by forest regulation: C6 Heaters Shovel (securely fastened) C20 Wheelchair forward facing (post 1993) Axe (securely fastened) \*Page number reference, Standards for School Buses in Montana (2002 Edition). \*\*\*\*Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver. 
\*\*Does not apply. \*\*\*New buses ordered after 08/15/02.\*\*\*\*\*Based on original capacity listed on the manufacturers certification tag found inside the bus. On first inspection, this bus is: On reinspection, this bus is: Approved Approved Not Approved Not Approved Inspecting Patrol Officer: Inspecting Patrol Officer: Date Date Badge No.



# **MONTANA HIGHWAY PATROL**

**School Bus Inspection** School Year 2006

State	
District	
County	
Patrol	
Contractor	

TR-13 Revised 11/04

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the

Highw	ay Patrol as soon as all defects are correc	ted.											
Instru	ictions to OPI from School District:	1											
	s bus has been sold, retired, or is no longe												
	ase make corrections noted below. Don't	black ou	ut the er	ror, OF	l may n	T							
OPI (	County # and County Name					Distri	ct Name						
	45 Sanders						Thor	npson Fa	lls Pub	Schle	3		
Vehic	le I.D. # (VIN) - Entire Number		Мс	odel Ye	ar	Licen		10001110	Rated C				
	, ,				_					. ,			
01	1GDKP32M0C3503922			198			E116	Dua Tura	. / 0 fe	18 : (see ? for definition)			
Chas	sis Make				Body Mal	(e			`				
	Chevrolet					The	omas	<b>✓</b> A [	∐B L	С	$\sqcup$ D		
Whee	el Chair Lift Equipped?	Whe	el Chai	r Lift Ed	quipped?	)							
✓ Y	es 🗆 No	✓ F	orwar	d Fac	ina	☐ Aisl	e Facing 🔲 N	ot Applica	able				
Type	of Fuel:						ontractor Owned If co			ractor's	name	is:	
✓ G						-							
<b>V</b> G	as   Diesel  Other						Mosher Transı	portation					
						CTION							
	<del>-</del>						GHWAY PATROL						
	Ihis	inspect			1s	t semes	ster 2nd seme	ster			A n.n.	rovo d	
Page	Items listed in the Standards	Yes	No	roved NA	Corr	Page	Items listed in	the Standar	rds	Yes	No App	roved NA	Corr
No.*	for School Buses in Montana	'		**	0011	No.*	for School Bus			100	140	**	0011
C17	Identification - front					C34	Belt cutter **** attach	ed					
C18	Head lamps					C18	Interior lamps						
C10	Color					C18	Ceiling - interior						
C18	Turn signal lamps - front	1			1	C21	Seating Floor						1
C18	Turn signal lamps - side (post 1987)  Red amber signals - front					C14	Aisle						
C18	Marker lamps - front					C22	Tools - storage						
C18	Windshield					C24	Windows						
C24	Windshield wipers					C13	Warning device						
C20	Exterior mirrors					C13	Buzzer emergency do	oor					
C3	Battery Congretor or olternator				1	C12 C18	Emergency door	****					-
C4 C11	Generator or alternator Service door					C18	Red amber signals - Turn signal lamps - re						
C6	Head lamp indicator					C18	Stop lamps	Jui					
C6	Horn					C18	Marker lamps - rear						
C20	Interior mirror					C19	Strobe light - rear ***						
C6	Speedometer						Identification - rear						
C2	Brakes				1	C4	Exhaust system (no l	eaks)					-
C21	Driver seat belt Steering gear					C5 C7	Fuel tank Tires (2/32" rear - 4/3	2" front mir	2.)				
C13	Fire extinguisher (5 lbs)					01	Cleanliness	Z HOHEHIII	,				
C13	First aid kit					C22	Stop arm						
C13	Body fluids kit					C5	No trailer hitch						
C11	Defroster						Required by forest r	_					
C6	Heaters Wheelsheir forward feeing (post 1903)						Shovel (securely fast						
C20 *Page n	Wheelchair forward facing (post 1993) umber reference, Standards for School Buses in I	Montana (	(2002 Ed	ition). *	***Bus dri	vers are r	Axe (securely fastene required to wear lap/should	,	tter attache	I d nearby	driver.	<u> </u>	
	not apply. ***New buses ordered after 08/15/02.*												
On fi	rst inspection, this bus is:					On re	inspection, this bus	is:					
	Approved						Approved						
	Not Approved						Not Approved						
Inspe	cting Patrol Officer:					Inspe	cting Patrol Officer:						
Bados	No	Date				Bados	e No			Date			
	ture of District Official					Date							
Jigila	and a significant control of					Date							



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

## **MONTANA HIGHWAY PATROL**

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

TR-13 Revised 11/04

Helena, MT 59620-2501 This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected. Instructions to OPI from School District: ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records. Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction. OPI County # and County Name District Name **Thompson Falls Pub Schls** 45 Sanders Vehicle I.D. # (VIN) - Entire Number Model Year Rated Capacity \*\*\*\*\* License # **1BAANCSH5PF054177** 1993 E110 Bus Type: (see ? for definition) Chassis Make Body Make  $\Box$  A  $\Box$  B  $\Box$  C **✓** D **Bluebird Bluebird** Wheel Chair Lift Equipped? Wheel Chair Lift Equipped? ☐ Yes ✓ No ☐ Forward Facing ☐ Aisle Facing ✓ Not Applicable Type of Fuel: Is Bus: District Owned Contractor Owned If contractor owned, contractor's name is: Gas ✓ Diesel Other Mosher Transportation INSPECTION TO BE FILLED OUT BY THE HIGHWAY PATROL 1st semester ✓ 2nd semester This inspection is for: Approved Approved NΑ Items listed in the Standards Items listed in the Standards Page No NA Yes No Yes Page Corr No.\* for School Buses in Montana No.\* for School Buses in Montana Belt cutter \*\*\*\* attached C17 Identification - front C34 C18 Head lamps C18 Interior lamps C18 C10 Color Ceiling - interior Turn signal lamps - front C18 C21 Seating Turn signal lamps - side (post 1987) C14 C18 Floor C18 Red amber signals - front C9 Aisle C18 Marker lamps - front C22 Tools - storage C18 Windshield C24 Windows C24 Windshield wipers C13 Warning device C20 Exterior mirrors C13 Buzzer emergency door C3 C12 Emergency door **Battery** C4 Generator or alternator C18 Red amber signals - rear Turn signal lamps - rear C11 C18 Service door C18 Stop lamps C6Head lamp indicator C6 C18 Marker lamps - rear Horn C20 Interior mirror C19 Strobe light - rear \*\*\* C6 Speedometer C17 Identification - rear Brakes C4 Exhaust system (no leaks) Driver seat belt Fuel tank Tires (2/32" rear - 4/32" front min.) Steering gear Fire extinguisher (5 lbs) Cleanliness C13 First aid kit C22 Stop arm No trailer hitch C13 Body fluids kit C5 C11 Defroster Required by forest regulation: C6 Heaters Shovel (securely fastened) C20 Wheelchair forward facing (post 1993) Axe (securely fastened) \*Page number reference, Standards for School Buses in Montana (2002 Edition). \*\*\*\*Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver. 
\*\*Does not apply. \*\*\*New buses ordered after 08/15/02.\*\*\*\*\*Based on original capacity listed on the manufacturers certification tag found inside the bus. On first inspection, this bus is: On reinspection, this bus is: Approved Approved Not Approved Not Approved Inspecting Patrol Officer: Inspecting Patrol Officer: Date Date Badge No.



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Holona, MT 59620-2501

#### **MONTANA HIGHWAY PATROL**

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

TR-13 Revised 11/04

Helena, MT 59620-2501 This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected. Instructions to OPI from School District: ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records. Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction. OPI County # and County Name District Name **Thompson Falls Pub Schls** 45 Sanders Vehicle I.D. # (VIN) - Entire Number Model Year Rated Capacity \*\*\*\*\* License # 4CDT7CR14R2700576 1994 E108 Bus Type: (see ? for definition) Chassis Make Body Make  $\Box$  A  $\Box$  B  $\Box$  C **✓** D **Thomas Thomas** Wheel Chair Lift Equipped? Wheel Chair Lift Equipped? ☐ Yes ✓ No ☐ Forward Facing ☐ Aisle Facing ✓ Not Applicable Type of Fuel: Is Bus: District Owned Contractor Owned If contractor owned, contractor's name is: Gas ✓ Diesel Other Mosher Transportation INSPECTION TO BE FILLED OUT BY THE HIGHWAY PATROL 1st semester ✓ 2nd semester This inspection is for: Approved Approved NΑ Items listed in the Standards Items listed in the Standards Page No NA Yes No Yes Page Corr No.\* for School Buses in Montana No.\* for School Buses in Montana Belt cutter \*\*\*\* attached C17 Identification - front C34 C18 Head lamps C18 Interior lamps C18 C10 Color Ceiling - interior Turn signal lamps - front C18 C21 Seating Turn signal lamps - side (post 1987) C14 C18 Floor C18 Red amber signals - front C9 Aisle C18 Marker lamps - front C22 Tools - storage C18 Windshield C24 Windows C24 Windshield wipers C13 Warning device C20 Exterior mirrors C13 Buzzer emergency door C3 C12 Emergency door **Battery** C4 Generator or alternator C18 Red amber signals - rear Turn signal lamps - rear C11 C18 Service door C18 Stop lamps C6Head lamp indicator C6 C18 Marker lamps - rear Horn C20 Interior mirror C19 Strobe light - rear \*\*\* C6 Speedometer C17 Identification - rear Brakes C4 Exhaust system (no leaks) Driver seat belt Fuel tank Tires (2/32" rear - 4/32" front min.) Steering gear Fire extinguisher (5 lbs) Cleanliness C13 First aid kit C22 Stop arm No trailer hitch C13 Body fluids kit C5 C11 Defroster Required by forest regulation: C6 Heaters Shovel (securely fastened) C20 Wheelchair forward facing (post 1993) Axe (securely fastened) \*Page number reference, Standards for School Buses in Montana (2002 Edition). \*\*\*\*Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver. 
\*\*Does not apply. \*\*\*New buses ordered after 08/15/02.\*\*\*\*\*Based on original capacity listed on the manufacturers certification tag found inside the bus. On first inspection, this bus is: On reinspection, this bus is: Approved Approved Not Approved Not Approved Inspecting Patrol Officer: Inspecting Patrol Officer: Date Date Badge No.



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

#### **MONTANA HIGHWAY PATROL**

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

TR-13 Revised 11/04

Helena, MT 59620-2501 This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected. Instructions to OPI from School District: ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records. Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction. OPI County # and County Name District Name **Thompson Falls Pub Schls** 45 Sanders Vehicle I.D. # (VIN) - Entire Number Model Year License # Rated Capacity \*\*\*\*\* 1HVBA1757DHB11596 1983 E111 Bus Type: (see ? for definition) Chassis Make Body Make  $\Box$  A  $\Box$  B ✓ C  $\Box$  D International **Thomas** Wheel Chair Lift Equipped? Wheel Chair Lift Equipped? ☐ Yes ✓ No ☐ Forward Facing ☐ Aisle Facing ✓ Not Applicable Type of Fuel: Is Bus: District Owned Contractor Owned If contractor owned, contractor's name is: Gas ✓ Diesel Other Mosher Transportation INSPECTION TO BE FILLED OUT BY THE HIGHWAY PATROL 1st semester ✓ 2nd semester This inspection is for: Approved Approved NΑ Items listed in the Standards Items listed in the Standards Page No NA Yes No Yes Page Corr No.\* for School Buses in Montana No.\* for School Buses in Montana Belt cutter \*\*\*\* attached C17 Identification - front C34 C18 Head lamps C18 Interior lamps C18 Ceiling - interior C10 Color Turn signal lamps - front C18 C21 Seating Turn signal lamps - side (post 1987) C14 C18 Floor C18 Red amber signals - front C9 Aisle C18 Marker lamps - front C22 Tools - storage C18 Windshield C24 Windows C24 Windshield wipers C13 Warning device C20 Exterior mirrors C13 Buzzer emergency door C3 C12 Emergency door **Battery** C4 Generator or alternator C18 Red amber signals - rear Turn signal lamps - rear C11 C18 Service door C18 Stop lamps C6Head lamp indicator C6 C18 Marker lamps - rear Horn C20 Interior mirror C19 Strobe light - rear \*\*\* C6 Speedometer C17 Identification - rear Brakes C4 Exhaust system (no leaks) Driver seat belt Fuel tank Tires (2/32" rear - 4/32" front min.) Steering gear Fire extinguisher (5 lbs) Cleanliness C13 First aid kit C22 Stop arm No trailer hitch C13 Body fluids kit C5 C11 Defroster Required by forest regulation: C6 Heaters Shovel (securely fastened) C20 Wheelchair forward facing (post 1993) Axe (securely fastened) \*Page number reference, Standards for School Buses in Montana (2002 Edition). \*\*\*\*Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver. 
\*\*Does not apply. \*\*\*New buses ordered after 08/15/02.\*\*\*\*\*Based on original capacity listed on the manufacturers certification tag found inside the bus. On first inspection, this bus is: On reinspection, this bus is: Approved Approved Not Approved Not Approved Inspecting Patrol Officer: Inspecting Patrol Officer: Date Date Badge No.



## **MONTANA HIGHWAY PATROL**

**School Bus Inspection** School Year 2006

State	
District	
County	
Patrol	
Contractor	

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the

Highw	ay Patrol as soon as all defects are correct	ted.											
	actions to OPI from School District:		rico Di	ooso da	oloto it fr	om OBI	's records						
This bus has been sold, retired, or is no longer in service. Please delete it Please make corrections noted below. Don't black out the error, OPI may													
OPI County # and County Name						ct Name	ection.						
45 Constant					Than	anaan Falla	Dub Cabl	_					
Vohio	45 Sanders le I.D. # (VIN) - Entire Number		Mo	odel Yea	or	Licen		npson Falls	ated Capacity				
venic	ie i.D. # (VIIV) - Littile Nullibei		IVIC	Juei i e	ai	LICEII	5 <del>C</del> #		aleu Capacit	,			
	1FDPJ74N7GVA22435			198	6		E113			72			
Chass	sis Make			В	ody Mał	се		Bus Type: (s	see ? for defin	ition)			
						<b>-</b> .		$\Box$ A $\Box$	В ✔С	$\Box$ D			
\\/haa	Ford Il Chair Lift Equipped?	Who	ol Chair	. I :ft Го	uipped?		omas						
				,			_						
☐ Ye	es 🗹 No	□ F	orwar	d Fac	ing [	AisI	e Facing 🛮 🗹 N	lot Applicabl	е				
Туре	of Fuel:	Is B	us:	Distric	t Owned	l ✓ C	ontractor Owned If co	ontractor owne	d, contractor's	name	is:		
□G	as ☑ Diesel ☐ Other												
	as Diesei - Other						Mosher Trans	portation					
					_	CTION							
							GHWAY PATROL						
	This	inspect			1s	t semes	ster 🗹 2nd seme	ster					
_	10 10 10 10 10 10	Tv.		roved	10	I 5	I 10 10 10 10		I.v	_ ' '	roved	To	
Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in for School Bus			No	NA **	Corr	
C17	Identification - front	1			1	C34	Belt cutter **** attach		-		+	+	
C18	Head lamps	1			1	C18	Interior lamps	icu		1	+	+	
C10	Color					C18	Ceiling - interior				+	+	
C18	Turn signal lamps - front	1				C21	Seating				1	†	
C18	Turn signal lamps - side (post 1987)					C14	Floor				1		
C18	Red amber signals - front					C9	Aisle				1	1	
C18	Marker lamps - front					C22	Tools - storage						
C18	Windshield					C24	Windows						
C24	Windshield wipers					C13	Warning device						
C20	Exterior mirrors					C13	Buzzer emergency d	oor					
C3	Battery	<u> </u>			<u> </u>	C12	Emergency door				┼	<del> </del>	
C4 C11	Generator or alternator Service door					C18	Red amber signals - Turn signal lamps - re				+	+	
C6	Head lamp indicator					C18	Stop lamps	eai			+	+	
C6	Horn	1			1	C18	Marker lamps - rear			1	+	+	
C20	Interior mirror					C19	Strobe light - rear ***				+	+	
C6	Speedometer					C17	Identification - rear				1	1	
C2	Brakes					C4	Exhaust system (no l	eaks)					
C21	Driver seat belt					C5	Fuel tank						
C7	Steering gear					C7	Tires (2/32" rear - 4/3	32" front min.)					
C13	Fire extinguisher (5 lbs)						Cleanliness				<u> </u>		
C13	First aid kit					C22	Stop arm						
C13	Body fluids kit					C5	No trailer hitch				₩		
C11	Defroster						Required by forest i			-	+	+	
C6 C20	Heaters Wheelchair forward facing (post 1993)						Shovel (securely fast Axe (securely fastene	,			+-	+	
	umber reference. Standards for School Buses in N	Montana i	(2002 Fd	ition) **	**Bus driv	vers are r			attached nearby	/ driver			
	not apply. ***New buses ordered after 08/15/02.**									, anver.			
On fi	st inspection, this bus is:					On re	einspection, this bus	is:					
	Approved						Approved						
	Not Approved						Not Approved						
Inspec	eting Patrol Officer:					Inspe	cting Patrol Officer:						

Badge No. Date Signature of District Official Date

TR-13 Revised 11/04



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

## **MONTANA HIGHWAY PATROL**

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

TR-13 Revised 11/04

Helena, MT 59620-2501 This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected. Instructions to OPI from School District: ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records. Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction. OPI County # and County Name District Name **Thompson Falls Pub Schls** 45 Sanders Vehicle I.D. # (VIN) - Entire Number Model Year Rated Capacity \*\*\*\*\* License # 1GBJ6P1G2MV100153 1990 E106 Bus Type: (see ? for definition) Chassis Make Body Make  $\square$  A  $\square$  B ✓ C  $\Box$  D Chevrolet Wayne Wheel Chair Lift Equipped? Wheel Chair Lift Equipped? ☐ Yes ✓ No ☐ Forward Facing ☐ Aisle Facing ✓ Not Applicable Type of Fuel: Is Bus: District Owned Contractor Owned If contractor owned, contractor's name is: Gas ✓ Diesel Other Mosher Transportation INSPECTION TO BE FILLED OUT BY THE HIGHWAY PATROL 1st semester ✓ 2nd semester This inspection is for: Approved Approved NΑ Items listed in the Standards Items listed in the Standards Page No NA Yes No Yes Page Corr No.\* for School Buses in Montana No.\* for School Buses in Montana Belt cutter \*\*\*\* attached C17 Identification - front C34 C18 Head lamps C18 Interior lamps C18 C10 Color Ceiling - interior Turn signal lamps - front C18 C21 Seating Turn signal lamps - side (post 1987) C14 C18 Floor C18 Red amber signals - front C9 Aisle C18 Marker lamps - front C22 Tools - storage C18 Windshield C24 Windows C24 Windshield wipers C13 Warning device C20 Exterior mirrors C13 Buzzer emergency door C3 C12 Emergency door **Battery** C4 Generator or alternator C18 Red amber signals - rear Turn signal lamps - rear C11 C18 Service door C18 Stop lamps C6Head lamp indicator C6 C18 Marker lamps - rear Horn C20 Interior mirror C19 Strobe light - rear \*\*\* C6 Speedometer C17 Identification - rear Brakes C4 Exhaust system (no leaks) Driver seat belt Fuel tank Tires (2/32" rear - 4/32" front min.) Steering gear Fire extinguisher (5 lbs) Cleanliness C13 First aid kit C22 Stop arm No trailer hitch C13 Body fluids kit C5 C11 Defroster Required by forest regulation: C6 Heaters Shovel (securely fastened) C20 Wheelchair forward facing (post 1993) Axe (securely fastened) \*Page number reference, Standards for School Buses in Montana (2002 Edition). \*\*\*\*Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver. 
\*\*Does not apply. \*\*\*New buses ordered after 08/15/02.\*\*\*\*\*Based on original capacity listed on the manufacturers certification tag found inside the bus. On first inspection, this bus is: On reinspection, this bus is: Approved Approved Not Approved Not Approved Inspecting Patrol Officer: Inspecting Patrol Officer: Date Date Badge No.



# **MONTANA HIGHWAY PATROL**

**School Bus Inspection** School Year 2006

State	
District	
County	
Patrol	
Contractor	

TR-13 Revised 11/04

	ay Patrol as soon as all defects are correct		11 20-10	7-101, 1	non. A	i vernere	3 not approved on m3	t inspection must t	ос тетторе	cica by				
Instru	ctions to OPI from School District:										-			
	s bus has been sold, retired, or is no longe		rice. Pl	ease de	elete it fr	om OPI	's records.							
Please make corrections noted below. Don't black out the error, OPI may n							eed to read it to make the correction.							
OPI County # and County Name				Distri	ct Name									
45 Constant					Thon	nnoon Follo Di	ıh Sahlı	•						
Vehic	45 Sanders le I.D. # (VIN) - Entire Number		Мс	del Ye	ar	Licen		npson Falls Pu	d Capacity					
V 01110	, ,		""			Licon		raio	a Capacity	•				
	1GBJ6P1G1MV100158			199			E107	D. T. T. (2.2.4	0 (	48				
Chas	sis Make				Body Ma	ke		Bus Type: (see	? for defin	ition)				
	Chevrolet					W	ayne	$\Box$ A $\Box$ B	✓ C	$\Box$ D				
Whee	l Chair Lift Equipped?	Whe	el Chai	r Lift Ed	quipped									
☐ Ye	es 🗹 No		orwar	d Fac	ina	Aisl	e Facing 🗹 N	ot Applicable						
	of Fuel:	Is Bu					ontractor Owned If co		ontractor's	name i	s.			
		10 5		Diotino					orniaotor c	, namo i	0.			
□G	as 🗹 Diesel 🗌 Other						Mosher Trans	portation						
					_	CTION								
							GHWAY PATROL							
	This	inspect			1s	t semes	ster 2nd seme	ster		A				
Page	Items listed in the Standards	Yes	Appi No	roved NA	Corr	Page	Items listed in	the Standards	Yes	App No	roved NA	Corr		
No.*	for School Buses in Montana	163	INO	**	Con	No.*	for School Bus		163	INO	**	Con		
C17	Identification - front					C34	Belt cutter **** attach	ed						
C18	Head lamps					C18	Interior lamps							
C10	Color					C18	Ceiling - interior				<u> </u>			
C18	Turn signal lamps - front					C21	Seating							
C18	Turn signal lamps - side (post 1987)  Red amber signals - front					C14 C9	Floor				<del> </del>			
C18	Marker lamps - front					C22	Aisle Tools - storage				╁			
C18	Windshield					C24	Windows			1				
C24	Windshield wipers					C13	Warning device							
C20	Exterior mirrors					C13	Buzzer emergency de	oor						
C3	Battery					C12	Emergency door							
C4	Generator or alternator					C18	Red amber signals -				<u> </u>			
C11	Service door				-	C18	Turn signal lamps - re	ear	_					
C6 C6	Head lamp indicator Horn					C18	Stop lamps Marker lamps - rear		_		┼──			
C20	Interior mirror					C19	Strobe light - rear ***				<del>                                     </del>			
C6	Speedometer					C17	Identification - rear			1				
C2	Brakes					C4	Exhaust system (no l	eaks)			<del></del>			
C21	Driver seat belt					C5	Fuel tank							
C7	Steering gear					C7	Tires (2/32" rear - 4/3	32" front min.)			<u> </u>			
C13	Fire extinguisher (5 lbs)					000	Cleanliness				<u> </u>			
C13	First aid kit				-	C22	Stop arm		_					
C13	Body fluids kit  Defroster					C5	No trailer hitch  Required by forest i	rogulation:	_		┼──			
C6	Heaters				+		Shovel (securely fast		+	<del> </del>	<del>                                     </del>			
	Wheelchair forward facing (post 1993)						Axe (securely fastene	,		1	t	1		
*Page ni	umber reference, Standards for School Buses in N						required to wear lap/shoul	der belts - cutter attac		driver.				
**Does r	not apply. ***New buses ordered after 08/15/02.**	***Based	on origii	nal capa	city listed	on the m	anufacturers certification	tag found inside the b	ous.					
On fi	st inspection, this bus is:					On re	einspection, this bus	is:				-		
	Approved						Approved							
	Not Approved						Not Approved							
Insped	cting Patrol Officer:					Inspe	cting Patrol Officer:							
Badge	No.	Date				Badge	e No.		Date					
	ture of District Official	_				Date			_					
•														



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

## **MONTANA HIGHWAY PATROL**

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

TR-13 Revised 11/04

Helena, MT 59620-2501 This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected. Instructions to OPI from School District: ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records. Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction. OPI County # and County Name District Name **Thompson Falls Pub Schls** 45 Sanders Vehicle I.D. # (VIN) - Entire Number Model Year Rated Capacity \*\*\*\*\* License # **1BAAHCSH8RF060257** 1994 E112 Bus Type: (see ? for definition) Chassis Make Body Make  $\Box$  A  $\Box$  B  $\Box$  C **✓** D **Bluebird Bluebird** Wheel Chair Lift Equipped? Wheel Chair Lift Equipped? ☐ Yes ✓ No ☐ Forward Facing ☐ Aisle Facing ✓ Not Applicable Type of Fuel: Is Bus: District Owned Contractor Owned If contractor owned, contractor's name is: Gas ✓ Diesel Other Mosher Transportation INSPECTION TO BE FILLED OUT BY THE HIGHWAY PATROL 1st semester ✓ 2nd semester This inspection is for: Approved Approved NΑ Items listed in the Standards Items listed in the Standards Page No NA Yes No Yes Page Corr No.\* for School Buses in Montana No.\* for School Buses in Montana Belt cutter \*\*\*\* attached C17 Identification - front C34 C18 Head lamps C18 Interior lamps C18 C10 Color Ceiling - interior Turn signal lamps - front C18 C21 Seating Turn signal lamps - side (post 1987) C14 C18 Floor C18 Red amber signals - front C9 Aisle C18 Marker lamps - front C22 Tools - storage C18 Windshield C24 Windows C24 Windshield wipers C13 Warning device C20 Exterior mirrors C13 Buzzer emergency door C3 C12 Emergency door **Battery** C4 Generator or alternator C18 Red amber signals - rear Turn signal lamps - rear C11 C18 Service door C18 Stop lamps C6Head lamp indicator C6 C18 Marker lamps - rear Horn C20 Interior mirror C19 Strobe light - rear \*\*\* C6 Speedometer C17 Identification - rear Brakes C4 Exhaust system (no leaks) Driver seat belt Fuel tank Tires (2/32" rear - 4/32" front min.) Steering gear Fire extinguisher (5 lbs) Cleanliness C13 First aid kit C22 Stop arm No trailer hitch C13 Body fluids kit C5 C11 Defroster Required by forest regulation: C6 Heaters Shovel (securely fastened) C20 Wheelchair forward facing (post 1993) Axe (securely fastened) \*Page number reference, Standards for School Buses in Montana (2002 Edition). \*\*\*\*Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver. 
\*\*Does not apply. \*\*\*New buses ordered after 08/15/02.\*\*\*\*\*Based on original capacity listed on the manufacturers certification tag found inside the bus. On first inspection, this bus is: On reinspection, this bus is: Approved Approved Not Approved Not Approved Inspecting Patrol Officer: Inspecting Patrol Officer: Date Date Badge No.



Inspecting Patrol Officer:

Signature of District Official

Date

Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Holona, MT 59620-2501

#### **MONTANA HIGHWAY PATROL**

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

Helena, MT 59620-2501 This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected. Instructions to OPI from School District: This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records. Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction. OPI County # and County Name District Name 45 Sanders **Trout Creek Elementary** Vehicle I.D. # (VIN) - Entire Number Model Year License # Rated Capacity \*\*\*\*\* 1GBJ6P1G2MV100153 1990 E106 Bus Type: (see ? for definition) Chassis Make Body Make  $\square$  A  $\square$  B ✓ C  $\Box$  D Chevrolet Wayne Wheel Chair Lift Equipped? Wheel Chair Lift Equipped? ☐ Yes ✓ No ☐ Forward Facing ☐ Aisle Facing ✓ Not Applicable Type of Fuel: Is Bus: District Owned Contractor Owned If contractor owned, contractor's name is: Gas ✓ Diesel Other Mosher Transportation INSPECTION TO BE FILLED OUT BY THE HIGHWAY PATROL 1st semester ✓ 2nd semester This inspection is for: Approved Approved NΑ Items listed in the Standards Items listed in the Standards Page No NA Yes No Yes Page Corr No.\* for School Buses in Montana No.\* for School Buses in Montana Belt cutter \*\*\*\* attached C17 Identification - front C34 C18 Head lamps C18 Interior lamps C18 C10 Color Ceiling - interior Turn signal lamps - front C18 C21 Seating Turn signal lamps - side (post 1987) C14 C18 Floor C18 Red amber signals - front C9 Aisle C18 Marker lamps - front C22 Tools - storage C18 Windshield C24 Windows C24 Windshield wipers C13 Warning device C20 Exterior mirrors C13 Buzzer emergency door C3 C12 Emergency door **Battery** C4 Generator or alternator C18 Red amber signals - rear Turn signal lamps - rear C11 C18 Service door C18 Stop lamps C6Head lamp indicator C6 C18 Marker lamps - rear Horn C20 Interior mirror C19 Strobe light - rear \*\*\* C6 Speedometer C17 Identification - rear Brakes C4 Exhaust system (no leaks) Driver seat belt Fuel tank Tires (2/32" rear - 4/32" front min.) Steering gear Fire extinguisher (5 lbs) Cleanliness C13 First aid kit C22 Stop arm No trailer hitch C13 Body fluids kit C5 C11 Defroster Required by forest regulation: C6 Heaters Shovel (securely fastened) C20 Wheelchair forward facing (post 1993) Axe (securely fastened) \*Page number reference, Standards for School Buses in Montana (2002 Edition). \*\*\*\*Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver. 
\*\*Does not apply. \*\*\*New buses ordered after 08/15/02.\*\*\*\*\*Based on original capacity listed on the manufacturers certification tag found inside the bus. On first inspection, this bus is: On reinspection, this bus is: Approved Approved Not Approved Not Approved

Inspecting Patrol Officer:

Badge No.

Date

TR-13 Revised 11/04



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Holona, MT 59620-2501

#### **MONTANA HIGHWAY PATROL**

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

TR-13 Revised 11/04

Helena, MT 59620-2501 This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected. Instructions to OPI from School District: ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records. Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction. OPI County # and County Name District Name 45 Sanders **Trout Creek Elementary** Vehicle I.D. # (VIN) - Entire Number Model Year License # Rated Capacity \*\*\*\*\* 1HVLPUGNIHH469087 1987 E109 Bus Type: (see ? for definition) Chassis Make Body Make  $\Box$  A  $\Box$  B ✓ C  $\Box$  D International **Thomas** Wheel Chair Lift Equipped? Wheel Chair Lift Equipped? ✓ Yes ☐ No ✓ Forward Facing ☐ Aisle Facing ☐ Not Applicable Type of Fuel: Is Bus: District Owned Contractor Owned If contractor owned, contractor's name is: Gas ✓ Diesel Other Mosher Transportation INSPECTION TO BE FILLED OUT BY THE HIGHWAY PATROL 1st semester ✓ 2nd semester This inspection is for: Approved Approved NΑ Items listed in the Standards Items listed in the Standards Page No NA Yes No Yes Page Corr No.\* for School Buses in Montana No.\* for School Buses in Montana Belt cutter \*\*\*\* attached C17 Identification - front C34 C18 Head lamps C18 Interior lamps C18 C10 Color Ceiling - interior Turn signal lamps - front C18 C21 Seating Turn signal lamps - side (post 1987) C14 C18 Floor C18 Red amber signals - front C9 Aisle C18 Marker lamps - front C22 Tools - storage C18 Windshield C24 Windows C24 Windshield wipers C13 Warning device C20 Exterior mirrors C13 Buzzer emergency door C3 C12 Emergency door **Battery** C4 Generator or alternator C18 Red amber signals - rear Turn signal lamps - rear C11 C18 Service door C18 Stop lamps C6Head lamp indicator C6 C18 Marker lamps - rear Horn C20 Interior mirror C19 Strobe light - rear \*\*\* C6 Speedometer C17 Identification - rear Brakes C4 Exhaust system (no leaks) Driver seat belt Fuel tank Tires (2/32" rear - 4/32" front min.) Steering gear Fire extinguisher (5 lbs) Cleanliness C13 First aid kit C22 Stop arm No trailer hitch C13 Body fluids kit C5 C11 Defroster Required by forest regulation: C6 Heaters Shovel (securely fastened) C20 Wheelchair forward facing (post 1993) Axe (securely fastened) \*Page number reference, Standards for School Buses in Montana (2002 Edition). \*\*\*\*Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver. 
\*\*Does not apply. \*\*\*New buses ordered after 08/15/02.\*\*\*\*\*Based on original capacity listed on the manufacturers certification tag found inside the bus. On first inspection, this bus is: On reinspection, this bus is: Approved Approved Not Approved Not Approved Inspecting Patrol Officer: Inspecting Patrol Officer: Date Date Badge No.



C11

C6

C20

Heaters

Wheelchair forward facing (post 1993)

Linda McCulloch, Superintendent Office of Public Instruction PO Box 202501

#### MONTANA HIGHWAY PATROL

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

TR-13 Revised 11/04

Helena, MT 59620-2501 This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected. Instructions to OPI from School District: ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records. Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction. OPI County # and County Name District Name 45 Sanders **Trout Creek Elementary** Vehicle I.D. # (VIN) - Entire Number Model Year License # Rated Capacity \*\*\*\*\* 2970 2002 e104 66 Bus Type: (see ? for definition) Chassis Make Body Make ПА □в ✓ C  $\Box$  D **Bluebird Bluebird** Wheel Chair Lift Equipped? Wheel Chair Lift Equipped? ☐ Yes ✓ No ☐ Forward Facing ☐ Aisle Facing ✓ Not Applicable Type of Fuel: Is Bus: District Owned Contractor Owned If contractor owned, contractor's name is: Gas ✓ Diesel Other **Mosher Transportation** INSPECTION TO BE FILLED OUT BY THE HIGHWAY PATROL 1st semester 2nd semester This inspection is for: Approved Approved Page Items listed in the Standards NΑ Items listed in the Standards No Yes No Yes NA Corr Page Corr No.\* for School Buses in Montana No.\* for School Buses in Montana Belt cutter \*\*\*\* attached C17 Identification - front C34 C18 Head lamps C18 Interior lamps Color C18 C10 Ceiling - interior Turn signal lamps - front C18 C21 Seating Turn signal lamps - side (post 1987) C18 C14 Floor C18 Red amber signals - front C9 Aisle C18 Marker lamps - front C22 Tools - storage C18 Windshield C24 Windows C24 Windshield wipers C13 Warning device C20 Exterior mirrors C13 Buzzer emergency door C3 C12 Emergency door Battery C4 Generator or alternator C18 Red amber signals - rear Turn signal lamps - rear C11 C18 Service door C18 C6Head lamp indicator Stop lamps C6 C18 Marker lamps - rear Horn C20 Interior mirror C19 Strobe light - rear \*\*\* C6 Speedometer C17 Identification - rear Brakes C4 Exhaust system (no leaks) Driver seat belt Fuel tank Tires (2/32" rear - 4/32" front min.) Steering gear Fire extinguisher (5 lbs) Cleanliness C13 First aid kit C22 Stop arm No trailer hitch C13 Body fluids kit C5 Defroster

\*Page number reference, Standards for School Buses in Montana (2002 Edition). \*\*\*\*Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver. 
\*\*Does not apply. \*\*\*New buses ordered after 08/15/02.\*\*\*\*\*Based on original capacity listed on the manufacturers certification tag found inside the bus.

	On reinspection, this bus is:	
	Approved	
	Not Approved	
_	Inspecting Patrol Officer:	_
Date	Badge No.	Date
	Date	
		Approved Not Approved Inspecting Patrol Officer: Badge No.

Required by forest regulation:

Shovel (securely fastened)

Axe (securely fastened)



Linda McCulloch, Superintendent Office of Public Instruction PO Box 202501 Helena, MT 59620-2501

## **MONTANA HIGHWAY PATROL**

**School Bus Inspection** School Year 2006

State	
District	
County	
Patrol	
Contractor	

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the

Highwa	ay Patrol as soon as all defects are correc	ted.										
	Instructions to OPI from School District:  This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.											
	ase make corrections noted below. Don't							ection.				
OPI County # and County Name						ct Name						
	45 Sanders						Tro	ut Creek Ele	montary			
Vehic	le I.D. # (VIN) - Entire Number		Mo	del Ye	ar	Licen			ed Capacity	, ****	-	-
Verilo	ie i.b. # (Viiv) - Elitile Numbel		IVIC	uei ie	ai	Liceii	3C #	IXA	eu Capacity			
	1PDPJ74N7GVA22435			198	6		E113			72		
Chass	sis Make			В	ody Mal	ке		Bus Type: (see	e? for defin	tion)		
	F 1							□а □в	✓ C	$\Box$ D		
Mhoo	Ford I Chair Lift Equipped?	\\/hc	ol Chair	· 1 if+ E	quipped?		omas					
							_					
□ Ye	es 🗹 No	□ F	orwar	d Fac	ing	Aisl	e Facing 🔽 N	lot Applicable				
Type	of Fuel:	Is B	us:	Distric	t Owned	<b>√</b> C	ontractor Owned If co	ontractor owned,	contractor's	name	is:	
□G	as ☑ Diesel ☐ Other											
	as 🗷 Diesei 🗆 Other						Mosher Trans	portation				
						CTION						
							GHWAY PATROL					
	This	s inspect			1s	t semes	ster 🗹 2nd seme	ster				
_		1	<del>- ' '</del>	oved	-	-			T		roved	T-
Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	for School Bus		Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attach	ned				
C18	Head lamps					C18	Interior lamps				<b>↓</b>	
C10	Color					C18	Ceiling - interior				<b>↓</b>	
C18	Turn signal lamps - front					C21	Seating				—	
C18	Turn signal lamps - side (post 1987)					C14	Floor					
C18	Red amber signals - front					C9	Aisle				<del> </del>	-
C18	Marker lamps - front Windshield					C22 C24	Tools - storage Windows				+	-
C24	Windshield wipers					C24	Warning device				+	+
C20	Exterior mirrors					C13	Buzzer emergency d	oor			+	-
C3	Battery	+			1	C12	Emergency door	001			+	+
C4	Generator or alternator					C18	Red amber signals -	rear			+	1
C11	Service door					C18	Turn signal lamps - r					
C6	Head lamp indicator					C18	Stop lamps					
C6	Horn					C18	Marker lamps - rear					
C20	Interior mirror					C19	Strobe light - rear ***					
C6	Speedometer					C17	Identification - rear					
C2	Brakes					C4	Exhaust system (no	eaks)			<b>↓</b>	
C21	Driver seat belt					C5	Fuel tank					
C7	Steering gear	-				C7	Tires (2/32" rear - 4/3	32" front min.)			┼	<del> </del>
C13	Fire extinguisher (5 lbs)					COO	Cleanliness				+	
C13	First aid kit Body fluids kit					C22 C5	Stop arm No trailer hitch				+	+
C11	Defroster Defroster				1	CS	Required by forest	regulation:	_		+-	+
C6	Heaters				1		Shovel (securely fast	_			+-	+
C20	Wheelchair forward facing (post 1993)				1		Axe (securely fastend	,			+-	+
	umber reference, Standards for School Buses in	Montana	(2002 Ed	ition). **	***Bus dri	vers are	. ,		tached nearby	driver.		
	not apply. ***New buses ordered after 08/15/02.											
On fi	st inspection, this bus is:					On re	einspection, this bus	is.				
	Approved						Approved					
	Not Approved						Not Approved					
	cting Patrol Officer:						cting Patrol Officer:					
Badge		Date				Badge			Date			
Dauge	. 110.	Pale				Dauut	, 11V.		Date			

TR-13 Revised 11/04



# **MONTANA HIGHWAY PATROL**

**School Bus Inspection** School Year 2006

State	
District	
County	
Patrol	
Contractor	

TR-13 Revised 11/04

	Highway Patrol as soon as all defects are corrected.												
Instru	ections to OPI from School District:												
Thi	s bus has been sold, retired, or is no longe	r in serv	ice. Ple	ease de	elete it fr	om OPI	's records.						
☐ Ple	ase make corrections noted below. Don't	black ou	ıt the eri	or, OF	l may ne	eed to read it to make the correction.							
OPI C	County # and County Name					Distri	ct Name						
	45 Sanders						Tro	ut Creek	Flome	ntarv			
Vehic	le I.D. # (VIN) - Entire Number		Мо	del Ye	ar	Licen		ut Creek	Rated C	Capacity	, ****		
V 01110	, ,			uo. 10	u.	Lioon			raiou	Japaony			
	1GBJ6PIGIMV100158			199			E107				48		
Chas	sis Make			E	Body Mal	ke		Bus Type	: (see ? f	or defini	tion)		
	Chevrolet					W	ayne	$\Box$ A	□ B [	<b>✓</b> C	$\Box$ D		
Whee	l Chair Lift Equipped?	Whe	el Chair	Lift Ed	quipped?		-yc						
□ Ye	es 🗹 No	$  \Box \Box$	orwar	d Fac	ina	Δiel	e Facing 🔽 N	ot Applica	ahle				
	of Fuel:	Is Bu								trootor'o	nomo	io:	
		IS DI	us.	DISTIIC	t Owned	1 <b>V</b> C	ontractor Owned If co	ontractor ow	mea, con	liacioi s	name	15.	
G	as 🗹 Diesel 🗌 Other						Mosher Trans	portation					
					INSPE	CTION							
		TC	BE FIL	LED (	OUT BY	THE HI	GHWAY PATROL						
	This	inspect	ion is fo	r:	1s	t semes	ster 2nd seme	ster					
			Appr	oved							App	roved	
Page	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in for School Bus			Yes	No	NA **	Corr
No.*	Identification - front				+	C34	Belt cutter **** attach		IIIa				-
C17	Head lamps				+	C18	Interior lamps	leu					
C10	Color					C18	Ceiling - interior						
C18	Turn signal lamps - front					C21	Seating						
C18	Turn signal lamps - side (post 1987)					C14	Floor						
C18	Red amber signals - front					C9	Aisle						
C18	Marker lamps - front					C22	Tools - storage						
C18	Windshield					C24	Windows						
C24 C20	Windshield wipers				-	C13	Warning device	00r					
C20	Exterior mirrors Battery				+	C12	Buzzer emergency de Emergency door	001					+
C4	Generator or alternator					C18	Red amber signals -	rear					
C11	Service door				†	C18	Turn signal lamps - re						1
C6	Head lamp indicator					C18	Stop lamps						
C6	Horn					C18	Marker lamps - rear						
C20	Interior mirror					C19	Strobe light - rear ***						
C6	Speedometer					C17	Identification - rear						
C2 C21	Brakes Driver seat belt				-	C4 C5	Exhaust system (no l	eaks)					
C7	Steering gear				+	C7	Fuel tank Tires (2/32" rear - 4/3	32" front min	1)				
C13	Fire extinguisher (5 lbs)				†	† ·	Cleanliness		/		1	<del>                                     </del>	1
C13	First aid kit					C22	Stop arm						
C13	Body fluids kit					C5	No trailer hitch						
C11	Defroster						Required by forest r						
C6	Heaters						Shovel (securely fast						
C20	Wheelchair forward facing (post 1993) umber reference, Standards for School Buses in N	Aontone (	(2002 E4:	tion\ *	***Buc d=:	vore ere	Axe (securely fastene		tor attacks	d noarby	driver	l	1
**Does r	umber reference, Standards for School Buses in Not apply. ***New buses ordered after 08/15/02.**	/iontana ( ***Based	(2002 Eal I on origin	uon). ** al capa	city listed	vers are r on the m	equired to wear lap/should anufacturers certification t	uer perts - cut tag found insi	ier attache de the bus.	ы пеагру	unver.		
					•								
	st inspection, this bus is: Approved						einspection, this bus Approved	15.					
	Not Approved						Not Approved						
	cting Patrol Officer:						cting Patrol Officer:						
-													
Badge	<u> </u>	Date				Badge No Date							
Signa	ture of District Official					Date							
						1							



Date

Signature of District Official

#### **MONTANA HIGHWAY PATROL**

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

Helena, MT 59620-2501 This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected. Instructions to OPI from School District: ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records. Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction. OPI County # and County Name District Name 45 Sanders **Trout Creek Elementary** Vehicle I.D. # (VIN) - Entire Number Model Year License # Rated Capacity \*\*\*\*\* 3922 1982 E116 Bus Type: (see ? for definition) Chassis Make Body Make **✓** B ПА  $\Box$  C  $\Box$  D Chevrolet **Thomas** Wheel Chair Lift Equipped? Wheel Chair Lift Equipped? ✓ Yes ☐ No ✓ Forward Facing ☐ Aisle Facing ☐ Not Applicable Type of Fuel: Is Bus: District Owned Contractor Owned If contractor owned, contractor's name is: ✓ Gas Diesel Other Mosher Transportation INSPECTION TO BE FILLED OUT BY THE HIGHWAY PATROL 1st semester ✓ 2nd semester This inspection is for: Approved Approved NΑ Items listed in the Standards Items listed in the Standards Page No NA Yes No Yes Page Corr No.\* for School Buses in Montana No.\* for School Buses in Montana Belt cutter \*\*\*\* attached C17 Identification - front C34 C18 Head lamps C18 Interior lamps C18 Ceiling - interior C10 Color Turn signal lamps - front C18 C21 Seating Turn signal lamps - side (post 1987) C14 C18 Floor C18 Red amber signals - front C9 Aisle C18 Marker lamps - front C22 Tools - storage C18 Windshield C24 Windows C24 Windshield wipers C13 Warning device C20 Exterior mirrors C13 Buzzer emergency door C3 C12 Emergency door **Battery** C4 Generator or alternator C18 Red amber signals - rear Turn signal lamps - rear C11 C18 Service door Head lamp indicator C18 Stop lamps C6C6 C18 Marker lamps - rear Horn C20 Interior mirror C19 Strobe light - rear \*\*\* C6 Speedometer C17 Identification - rear Brakes C4 Exhaust system (no leaks) Driver seat belt Fuel tank Tires (2/32" rear - 4/32" front min.) Steering gear Fire extinguisher (5 lbs) Cleanliness C13 First aid kit C22 Stop arm No trailer hitch C13 Body fluids kit C5 C11 Defroster Required by forest regulation: C6 Heaters Shovel (securely fastened) C20 Wheelchair forward facing (post 1993) Axe (securely fastened) \*Page number reference, Standards for School Buses in Montana (2002 Edition). \*\*\*\*Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver. 
\*\*Does not apply. \*\*\*New buses ordered after 08/15/02.\*\*\*\*\*Based on original capacity listed on the manufacturers certification tag found inside the bus. On first inspection, this bus is: On reinspection, this bus is: Approved Approved Not Approved Not Approved Inspecting Patrol Officer: Inspecting Patrol Officer:

Badge No.

Date

TR-13 Revised 11/04



# **MONTANA HIGHWAY PATROL**

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

TR-13 Revised 11/04

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Highw	ay Patrol as soon as all defects are correct	ted.						-					
Instru	ictions to OPI from School District	:											
Thi	s bus has been sold, retired, or is no longe	er in serv	ice. Pl	ease de	elete it fr	om OPI	s records.						
☐ Ple	ase make corrections noted below. Don't	black ou	ut the er	ror, OF	l may n	need to read it to make the correction.							
OPI C	County # and County Name					Distri	ct Name						
	45.0						_						
\/alaia	45 Sanders			1 V -		1:		ut Creek Ele	ementary	*****			
venic	le I.D. # (VIN) - Entire Number		IVIC	odel Ye	ar	Licen	se #	R	ated Capacit	у			
	6096			198	3		E105			60			
Chas	sis Make		•	E	Body Mal	ке		Bus Type: (se	ee ? for defir	nition)			
						_		$\Box$ A $\Box$ I	B <b>∨</b> C	$\Box$ D			
\\/hoc	Ford I Chair Lift Equipped?	\//bc	ol Chai	r I ift E	quipped?		perior						
□ Ye	es 🗹 No		orwar	d Fac	ing	AisI	e Facing 🔛 N	ot Applicable	Э				
Туре	of Fuel:	Is B	us:	Distric	t Owned	d 🗸 C	ontractor Owned If co	ontractor owned	l, contractor	s name	is:		
<b>✓</b> G	as $\square$ Diesel $\square$ Other						Machar Trans	nortotion					
							Mosher Trans	portation					
		т.	S DE EI	LLED		CTION	CUMAY DATEOL						
	This	inspect				t semes	GHWAY PATROL ster ✓ 2nd seme	stor					
	Tills	inspeci		roved	18	it semes	Zilu Seille:	Stei		Anr	oroved		
Page	Items listed in the Standards	Yes	No	NA	Corr	Page	Items listed in	the Standards	Yes	No	NA	Corr	
No.*	for School Buses in Montana			**		No.*	for School Bus	es in Montana			**		
C17	Identification - front					C34	Belt cutter **** attach	ed					
C18	Head lamps					C18	Interior lamps						
C10	Color					C18	Ceiling - interior			+			
C18	Turn signal lamps - front					C21	Seating Floor			+	+		
C18	Turn signal lamps - side (post 1987) Red amber signals - front					C14	Aisle			+-	+		
C18	Marker lamps - front	1			+	C22	Tools - storage			+	+-		
C18	Windshield					C24	Windows				1		
C24	Windshield wipers					C13	Warning device						
C20	Exterior mirrors					C13	Buzzer emergency de	oor					
C3	Battery					C12	Emergency door			+	<del> </del>		
C4	Generator or alternator	1			1	C18	Red amber signals -			+-	┼		
C11 C6	Service door Head lamp indicator	+			+	C18	Turn signal lamps - re Stop lamps	ear		+	+-	+	
C6	Horn				+	C18	Marker lamps - rear			+	+-		
C20	Interior mirror				1	C19	Strobe light - rear ***			+			
C6	Speedometer					C17	Identification - rear						
C2	Brakes					C4	Exhaust system (no l	eaks)					
C21	Driver seat belt				1	C5	Fuel tank	2011		∔	<del> </del>	1	
C7	Steering gear	<u> </u>			+	C7	Tires (2/32" rear - 4/3	32" front min.)		+			
C13	Fire extinguisher (5 lbs) First aid kit	1	}	-	+	C22	Cleanliness Stop arm			+-	+-	+	
C13	Body fluids kit				+	C5	No trailer hitch			+	+-		
C11	Defroster						Required by forest r	regulation:		1	1		
C6	Heaters						Shovel (securely fast	ened)					
C20	Wheelchair forward facing (post 1993)						Axe (securely fastene	,					
	umber reference, Standards for School Buses in not apply. ***New buses ordered after 08/15/02.*									y driver.			
			og	30,00	,	1			- = = -				
	st inspection, this bus is:						einspection, this bus	is:					
	Approved Not Approved						Approved Not Approved						
	cting Patrol Officer:						cting Patrol Officer:						
mapet													
Badge		Date				Badge No Date							
Signa	ture of District Official					Date							



# **MONTANA HIGHWAY PATROL**

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

TR-13 Revised 11/04

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Highway Patrol as soon as all defects are corrected.													
	actions to OPI from School Districts bus has been sold, retired, or is no longer	-	rico Di	2000 d	alata it fr	om ODI	la racorda						
	, ,							ection					
Please make corrections noted below. Don't black out the error, OPI may nee OPI County # and County Name					District Name								
4F Condoro						Devadios Flamontonio							
45 Sanders  Vehicle I.D. # (VIN) - Entire Number  Model Year					Paradise Elementary License # Rated Capacity *****								
Vehicle I.D. # (VIN) - Entire Number Model Year					License # Rated Capacity ******								
	1GDJ6P1B6EV522486			198	34		35TE		65				
Chas	sis Make			Е	Body Mal	ake Bus Type: (see ? for definition)							
	GMC					W	Ward □ A □ B ☑ C □ D						
Whee	el Chair Lift Equipped?	Whe	el Chai	Lift E	quipped?								
							a Fasina - M N	ملطمعانممالم					
☐ Y			orwar					ot Applicable					
Туре	of Fuel:	Is B	us:	Distri	ct Owned	✓ C	ontractor Owned If co	ontractor owned, co	ontractor's	name	is:		
<b>✓</b> G	as $\square$ Diesel $\square$ Other						Lisa K Fre	ench					
					INSPE	CTION							
		TO	BE FI	LLED	OUT BY	THE HI	GHWAY PATROL						
	This	inspect	ion is fo	r:	1s	t semes	ster 🗹 2nd semes	ster					
			Аррі	oved						App	roved		
Page	Items listed in the Standards	Yes	No	NA	Corr	Page	Items listed in		Yes	No	NA	Corr	
No.*	for School Buses in Montana			**		No.*	for School Bus				**		
C17	Identification - front					C34	Belt cutter **** attach	ed			—		
C18	Head lamps					C18	Interior lamps				<b>↓</b>		
C10	Color					C18	Ceiling - interior				+		
C18	Turn signal lamps - front Turn signal lamps - side (post 1987)		1			C21 Seating C14 Floor					+	+	
C18	Red amber signals - front					C9 Aisle					+		
C18	Marker lamps - front	1				C22 Tools - storage					+		
C18	Windshield					C24 Windows					+		
C24	Windshield wipers					C13 Warning device							
C20	Exterior mirrors					C13 Buzzer emergency door							
C3	Battery					C12 Emergency door							
C4	Generator or alternator					C18 Red amber signals - rear							
C11	Service door					C18 Turn signal lamps - rear				<u> </u>			
C6	Head lamp indicator					C18 Stop lamps				<b>↓</b>			
C6	Horn					C18 Marker lamps - rear							
C20 C6	Interior mirror					C19 C17	Strobe light - rear *** Identification - rear				<del> </del>		
C2	Speedometer Brakes	1				C17	Exhaust system (no l	eaks)			+		
C21	Driver seat belt	1			1	C5	Fuel tank	canoj			+	+	
C7	Steering gear					C7	Tires (2/32" rear - 4/3	2" front min.)			+		
C13	Fire extinguisher (5 lbs)				1		Cleanliness				1		
C13	First aid kit					C22	Stop arm						
C13	Body fluids kit					C5	No trailer hitch						
C11	Defroster						Required by forest r	egulation:					
C6	Heaters						Shovel (securely fast						
C20	Wheelchair forward facing (post 1993)						Axe (securely fastene				<u> </u>		
	umber reference, Standards for School Buses in I not apply. ***New buses ordered after 08/15/02.**									driver.			
							einspection, this bus						
	rst inspection, this bus is: Approved						Approved	iə.					
	Not Approved						Not Approved						
	cting Patrol Officer:						cting Patrol Officer:						
-													
	Badge No Date				Badge	e No		Date _					
Signa	ture of District Official					Date							



# **MONTANA HIGHWAY PATROL**

**School Bus Inspection** School Year 2006

State	
District	
County	
Patrol	
Contractor	

TR-13 Revised 11/04

	ay Patrol as soon as all defects are correct		11 20-10-	101, 1	ICA. AII	vernicie	s not approved on ms	i irispection	must be	remspe	cied by	uie	
Instru	ctions to OPI from School District:												
Thi	s bus has been sold, retired, or is no longe	r in serv	ice. Ple	ase de	elete it fr	om OPI	's records.						
☐ Ple	ase make corrections noted below. Don't	black ou	ut the err	or, OF	l may ne	ed to re	ead it to make the corr	ection.					
OPI County # and County Name					Distri	ct Name							
AF Condorn						Davadica Flamentam.							
45 Sanders  Vehicle I.D. # (VIN) - Entire Number Model Year						Paradise Elementary License # Rated Capacity *****							
Vehicle I.B. # (VIIV) - Entire Number						License # Rated Capacity							
1BAAHCSH2LFO33630 1990						35TE 65							
Chassis Make Body Make						ke Bus Type: (see ? for definition)							
	Bluebird					Other							
Whee	Chair Lift Equipped?	Whe	el Chair	Lift E	quipped?			l					
□ Ye	es 🗹 No		orwar	d Eac	ina	Λicl	e Facing 🔽 N	ot Applica	ablo				
	of Fuel:	-								ro otorio			
		Is Bu	us.	District Owned  Contractor Owned If contractor owned, contractor's name is:									
G	as 🗹 Diesel 🗌 Other						Lisa K Fre	ench					
					INSPE	CTION							
		TC	BE FIL	LED (	OUT BY	THE HI	GHWAY PATROL						
	This	inspect	ion is fo	r:	1s	t semes	ster 🗸 2nd seme	ster					
		1	Appr									roved	
Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in for School Bus			Yes	No	NA **	Corr
C17	Identification - front				+	C34	Belt cutter **** attach		ıııa				
C18	Head lamps				+	C18	Interior lamps	lcu					
C10	Color					C18	Ceiling - interior						
C18	Turn signal lamps - front					C21 Seating							
C18	Turn signal lamps - side (post 1987)					C14							
C18	Red amber signals - front				1	C9 Aisle							
C18	Marker lamps - front				+	C22 Tools - storage C24 Windows							
C18 C24	Windshield Windshield wipers				+	C24	Warning device						
C20	Exterior mirrors				+	C13 Buzzer emergency door							
C3	Battery				1	C12 Emergency door							
C4	Generator or alternator					C18 Red amber signals - rear							
C11	Service door					C18 Turn signal lamps - rear							
C6	Head lamp indicator				-	C18	Stop lamps						
C6 C20	Horn Interior mirror				+	C18 C19	Marker lamps - rear Strobe light - rear ***						
C6	Speedometer				+	C17	Identification - rear						
C2	Brakes					C4	Exhaust system (no l	eaks)					
C21	Driver seat belt					C5	Fuel tank	,					
C7	Steering gear					C7	Tires (2/32" rear - 4/3	32" front mir	ı.)				
C13	Fire extinguisher (5 lbs)						Cleanliness						
C13	First aid kit				-	C22	Stop arm						
C13	Body fluids kit Defroster				+	C5	No trailer hitch  Required by forest r	rogulation:					
C6	Heaters				+		Shovel (securely fast						
C20	Wheelchair forward facing (post 1993)						Axe (securely fastene						
*Page ni	ımber reference, Standards for School Buses in M						equired to wear lap/shoul	der belts - cut			driver.	•	•
**Does r	ot apply. ***New buses ordered after 08/15/02.**	***Based	l on origin	al capa	city listed	on the m	anufacturers certification t	tag found insi	de the bus.				
On fi	st inspection, this bus is:					On re	inspection, this bus	is:	<del>-</del>				
	Approved						Approved						
	Not Approved						Not Approved						
Insped	ting Patrol Officer:					Inspe	cting Patrol Officer:						
Badge No. Date					Badge No Date								
Signature of District Official				Date									



# **MONTANA HIGHWAY PATROL**

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

TR-13 Revised 11/04

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Highway Patrol as soon as all defects are corrected.														
Instructions to OPI from School District:														
Thi	s bus has been sold, retired, or is no longe	r in serv	ice. Ple	ease d	elete it fi	om OPI	's records.							
Please make corrections noted below. Don't black out the error, OPI may no														
OPI County # and County Name					District Name									
or roomly want county manie														
45 Sanders						Dixon Elementary								
Vehicle I.D. # (VIN) - Entire Number Model Year						License # Rated Capacity *****								
1BAACCSUZNE040375 1002						A499 6					66			
1BAAGCSH7NF049375         1992           Chassis Make         Body Make														
Criassis Make														
	Other						ebird	$\square$ A $\square$ B	□с	<b>✓</b> D				
Whee	el Chair Lift Equipped?	Whe	el Chai	r Lift E	quipped	?								
	es 🗹 No	I □ F	orwar	d Fac	cina	Aisl	e Facing 🔽 N	lot Applicable						
	of Fuel:						<u>-</u>		ntractor's	name	ie:			
		13 D	Bus: ☐ District Owned ✔ Contractor Owned If contractor owned, contractor's name is:											
$\Box$ G	as 🗹 Diesel 🗌 Other						Marianne Jo	hnson						
					INSPE	CTION								
		TO	BE FII	LLED	_		GHWAY PATROL							
	This	inspect	ion is fo	r:	19	st semes	ster 🗸 2nd seme	ster						
		•		roved			<del></del>			App	roved			
Page	Items listed in the Standards	Yes	No	NA	Corr	Page	Items listed in	the Standards	Yes	No	NA	Corr		
No.*	for School Buses in Montana			**		No.*	for School Bus				**			
C17	Identification - front					C34	Belt cutter **** attach	ned		<u> </u>				
C18	Head lamps					C18	Interior lamps				—			
C10	Color					C18	Ceiling - interior			<u> </u>				
C18	Turn signal lamps - front	-				C21	Seating		+	<del>                                     </del>	+			
C18	Turn signal lamps - side (post 1987)				C14 Floor C9 Aisle			-	<del> </del>	+				
C18	Red amber signals - front  Marker lamps - front	+				C22	Tools - storage		+	+	+	+		
C18	Windshield					C24	Windows		+	+	+			
C24	Windshield wipers					C13	Warning device			1	+			
C20	Exterior mirrors				1	C13	Buzzer emergency d	oor	†	1	+			
C3	Battery					C12	Emergency door			1				
C4	Generator or alternator					C18	C18 Red amber signals - rear							
C11	Service door					C18	Turn signal lamps - re							
C6	Head lamp indicator					C18	Stop lamps							
C6	Horn					C18 Marker lamps - rear					$\bot$			
C20	Interior mirror					C19	Strobe light - rear ***			<u> </u>				
C6	Speedometer	-				C17	Identification - rear	11	+	<del> </del>	+			
C2	Brakes					C4	Exhaust system (no l	leaks)		+	+			
C21	Driver seat belt Steering gear	1			1	C5 C7	Fuel tank Tires (2/32" rear - 4/3	32" front min \	+	+	+	+		
C13	Fire extinguisher (5 lbs)					C/	Cleanliness	)2 HOH HIII.)	+	+	+			
C13	First aid kit					C22	Stop arm			1	+			
C13	Body fluids kit	†				C5	No trailer hitch		†	1	+			
C11	Defroster						Required by forest i	regulation:		1				
C6	Heaters	1					Shovel (securely fast	_		1	1			
C20	Wheelchair forward facing (post 1993)						Axe (securely fastene							
	umber reference, Standards for School Buses in I									driver.				
**Does r	not apply. ***New buses ordered after 08/15/02.**	****Based	on origin	nal capa	acity listed	on the m	anutacturers certification	tag found inside the bu	S.					
On first inspection, this bus is:  On reinspection, this bus is:														
	Approved						Approved							
	Not Approved						Not Approved							
Inspe	cting Patrol Officer:					Inspe	cting Patrol Officer:							
	Badge No Date				Badge No Date									
Signa	Signature of District Official					Date								



Date

Signature of District Official

### **MONTANA HIGHWAY PATROL**

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

School Year 2006 Helena, MT 59620-2501 This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected. Instructions to OPI from School District: ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records. Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction. OPI County # and County Name District Name **Noxon Public Schools** 45 Sanders Vehicle I.D. # (VIN) - Entire Number Model Year License # Rated Capacity \*\*\*\*\* 4DRBRABP34B963544 2004 353 Bus Type: (see ? for definition) Chassis Make Body Make Пв ПА ✓ C  $\Box$  D International International Wheel Chair Lift Equipped? Wheel Chair Lift Equipped? ☐ Yes ✓ No ☐ Forward Facing ☐ Aisle Facing ✓ Not Applicable Type of Fuel: Is Bus: ✓ District Owned ☐ Contractor Owned If contractor owned, contractor's name is: Gas ✓ Diesel Other INSPECTION TO BE FILLED OUT BY THE HIGHWAY PATROL 1st semester ✓ 2nd semester This inspection is for: Approved Approved NΑ Items listed in the Standards Items listed in the Standards Page No NA Page Yes No Yes Corr Corr No.\* for School Buses in Montana No.\* for School Buses in Montana Belt cutter \*\*\*\* attached C17 Identification - front C34 C18 Head lamps C18 Interior lamps C18 C10 Color Ceiling - interior Turn signal lamps - front C18 C21 Seating Turn signal lamps - side (post 1987) C14 C18 Floor C18 Red amber signals - front C9 Aisle C18 Marker lamps - front C22 Tools - storage C18 Windshield C24 Windows C24 Windshield wipers C13 Warning device C20 Exterior mirrors C13 Buzzer emergency door C3 C12 Emergency door **Battery** C4 Generator or alternator C18 Red amber signals - rear Turn signal lamps - rear C11 C18 Service door C18 Stop lamps C6Head lamp indicator C6 C18 Marker lamps - rear Horn C20 Interior mirror C19 Strobe light - rear \*\*\* C6 Speedometer C17 Identification - rear Brakes C4 Exhaust system (no leaks) Driver seat belt Fuel tank Tires (2/32" rear - 4/32" front min.) Steering gear Fire extinguisher (5 lbs) Cleanliness C13 First aid kit C22 Stop arm No trailer hitch C13 Body fluids kit C5 C11 Defroster Required by forest regulation: C6 Heaters Shovel (securely fastened) C20 Wheelchair forward facing (post 1993) Axe (securely fastened) \*Page number reference, Standards for School Buses in Montana (2002 Edition). \*\*\*\*Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver. 
\*\*Does not apply. \*\*\*New buses ordered after 08/15/02.\*\*\*\*\*Based on original capacity listed on the manufacturers certification tag found inside the bus. On first inspection, this bus is: On reinspection, this bus is: Approved Approved Not Approved Not Approved Inspecting Patrol Officer: Inspecting Patrol Officer:

Badge No.

Date

TR-13 Revised 11/04



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

### **MONTANA HIGHWAY PATROL**

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

Helena, MT 59620-2501 This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected. Instructions to OPI from School District: ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records. Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction. OPI County # and County Name District Name **Noxon Public Schools** 45 Sanders Vehicle I.D. # (VIN) - Entire Number Model Year Rated Capacity \*\*\*\*\* License # **4UZ3CFAA8YCG46250** 2000 289 Bus Type: (see ? for definition) Chassis Make Body Make Пв ПА ✓ C  $\Box$  D Freightliner **Thomas** Wheel Chair Lift Equipped? Wheel Chair Lift Equipped? ☐ Yes ✓ No ☐ Forward Facing ☐ Aisle Facing ✓ Not Applicable Type of Fuel: Is Bus: ✓ District Owned ☐ Contractor Owned If contractor owned, contractor's name is: Gas ✓ Diesel Other INSPECTION TO BE FILLED OUT BY THE HIGHWAY PATROL 1st semester ✓ 2nd semester This inspection is for: Approved Approved Page NΑ Items listed in the Standards Items listed in the Standards No NA Page Yes No Yes Corr Corr No.\* for School Buses in Montana No.\* for School Buses in Montana Belt cutter \*\*\*\* attached C17 Identification - front C34 C18 Head lamps C18 Interior lamps C18 Ceiling - interior C10 Color Turn signal lamps - front C18 C21 Seating Turn signal lamps - side (post 1987) C14 C18 Floor C18 Red amber signals - front C9 Aisle C18 Marker lamps - front C22 Tools - storage C18 Windshield C24 Windows C24 Windshield wipers C13 Warning device C20 Exterior mirrors C13 Buzzer emergency door C3 C12 Emergency door **Battery** C4 Generator or alternator C18 Red amber signals - rear Turn signal lamps - rear C11 C18 Service door C18 Stop lamps C6Head lamp indicator C6 C18 Marker lamps - rear Horn C20 Interior mirror C19 Strobe light - rear \*\*\* C6 Speedometer C17 Identification - rear Brakes C4 Exhaust system (no leaks) Driver seat belt Fuel tank Tires (2/32" rear - 4/32" front min.) Steering gear Fire extinguisher (5 lbs) Cleanliness C13 First aid kit C22 Stop arm No trailer hitch C13 Body fluids kit C5 C11 Defroster Required by forest regulation: C6 Heaters Shovel (securely fastened) C20 Wheelchair forward facing (post 1993) Axe (securely fastened) \*Page number reference, Standards for School Buses in Montana (2002 Edition). \*\*\*\*Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver. 
\*\*Does not apply. \*\*\*New buses ordered after 08/15/02.\*\*\*\*\*Based on original capacity listed on the manufacturers certification tag found inside the bus. On first inspection, this bus is: On reinspection, this bus is: Approved Approved Not Approved Not Approved Inspecting Patrol Officer: Inspecting Patrol Officer: Date Date Badge No.



# **MONTANA HIGHWAY PATROL**

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

TR-13 Revised 11/04

1 ligitw	ay Fatiol as soon as all delects are correct	.cu.										_	
	ictions to OPI from School District:		ice Ple	3SE (	delete it fr	om OPI	's records						
This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.  Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.													
	County # and County Name	2.401. 00		,, 0		District Name							
45 Sanders							No	xon Pub	lic Sch	oole			
Vehicle I.D. # (VIN) - Entire Number Model Year						Licen		XOII FUD	Rated C		****	-	-
Verilo	, ,		IVIOC			Licen			Rateu	лараспу			
	4UZAAXBW11CH68788			20	00		297	D T	, 0,		46		
Chas	sis Make				Body Mal	ке		Bus Type	•		,		
	Other					The	omas	$\Box$ A	□В	✓ C	$\Box$ D		
Whee	l Chair Lift Equipped?	Whe	el Chair	Lift E	Equipped?	>							
□ Ye	es 🗹 No	│□F	orward	l Fa	cina	☐ Aisl	e Facing 🗹 N	ot Applica	able				
Type	of Fuel:	Is Bu			rict Owned		ontractor Owned If co			tractor's	name i	s:	
									,				
□G	as 🗹 Diesel 🗌 Other												
						CTION							
					_		GHWAY PATROL						
	This	inspect	ion is for			t semes	ster 🗹 2nd semes	ster					
Page	Items listed in the Standards	Yes	Appro	ved NA	Corr	Page	Items listed in	the Standa	rdo	Yes	App No	roved NA	Corr
No.*	for School Buses in Montana	165	INO	**	Con	No.*	for School Bus			165	INO	**	Con
C17	Identification - front					C34	Belt cutter **** attach	ed					
C18	Head lamps					C18	Interior lamps						
C10	Color					C18	Ceiling - interior						
C18	Turn signal lamps - front					C21	Seating						
C18	Turn signal lamps - side (post 1987)					C14	Floor					<u> </u>	<u> </u>
C18	Red amber signals - front					C9	Aisle					<b>↓</b>	—
C18	Marker lamps - front					C22	Tools - storage					<b>↓</b>	<b>_</b>
C18	Windshield					C24	Windows					—	<del> </del>
C24 C20	Windshield wipers  Exterior mirrors					C13	Warning device Buzzer emergency do	oor				+	+
C3	Battery					C12	Emergency door	JUI				+	+
C4	Generator or alternator					C18	Red amber signals -	rear					+
C11	Service door	1				C18	Turn signal lamps - re				1	<del>†                                      </del>	†
C6	Head lamp indicator					C18	Stop lamps					1	
C6	Horn					C18	Marker lamps - rear						
C20	Interior mirror					C19	Strobe light - rear ***						
C6	Speedometer					C17	Identification - rear					<u> </u>	
C2	Brakes					C4	Exhaust system (no l	eaks)				<b>↓</b>	<b>_</b>
C21 C7	Driver seat belt Steering gear					C5 C7	Fuel tank Tires (2/32" rear - 4/3	2" front mir	2 )			<del> </del>	+
C13	Fire extinguisher (5 lbs)					C/	Cleanliness	2 11011111111	1.)			+	+
C13	First aid kit					C22	Stop arm						+
C13	Body fluids kit					C5	No trailer hitch					<del>                                     </del>	†
C11	Defroster						Required by forest r	egulation:					1
C6	Heaters						Shovel (securely fast	ened)					
C20	Wheelchair forward facing (post 1993)						Axe (securely fastene						
	umber reference, Standards for School Buses in I not apply. ***New buses ordered after 08/15/02.**										driver.		
On fi	st inspection, this bus is:					On re	einspection, this bus	is:					
	Approved					l	Approved						
☐ Not Approved				Not Approved									
	cting Patrol Officer:						cting Patrol Officer:						
Badge		Date				Badge No Date							
		- Daile				Date				- Juil			
Signature of District Official				Date									



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Holona, MT 59620-2501

### **MONTANA HIGHWAY PATROL**

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

TR-13 Revised 11/04

School Year 2006 Helena, MT 59620-2501 This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected. Instructions to OPI from School District: ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records. Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction. OPI County # and County Name District Name **Noxon Public Schools** 45 Sanders Vehicle I.D. # (VIN) - Entire Number Model Year License # Rated Capacity \*\*\*\*\* **1BAAHCSH5NF049372** 1992 97 Bus Type: (see ? for definition) Chassis Make Body Make  $\square$  A  $\square$  B  $\Box$  C **✓** D **Bluebird Bluebird** Wheel Chair Lift Equipped? Wheel Chair Lift Equipped? ☐ Yes ✓ No ☐ Forward Facing ☐ Aisle Facing ✓ Not Applicable Type of Fuel: Is Bus: District Owned Contractor Owned If contractor owned, contractor's name is: Gas ✓ Diesel Other INSPECTION TO BE FILLED OUT BY THE HIGHWAY PATROL 1st semester ✓ 2nd semester This inspection is for: Approved Approved NΑ Items listed in the Standards Items listed in the Standards Page No NA Page Yes No Yes Corr Corr No.\* for School Buses in Montana No.\* for School Buses in Montana Belt cutter \*\*\*\* attached C17 Identification - front C34 C18 Head lamps C18 Interior lamps C18 Ceiling - interior C10 Color Turn signal lamps - front C18 C21 Seating Turn signal lamps - side (post 1987) C14 C18 Floor C18 Red amber signals - front C9 Aisle C18 Marker lamps - front C22 Tools - storage C18 Windshield C24 Windows C24 Windshield wipers C13 Warning device C20 Exterior mirrors C13 Buzzer emergency door C3 C12 Emergency door **Battery** C4 Generator or alternator C18 Red amber signals - rear Turn signal lamps - rear C11 C18 Service door C18 Stop lamps C6Head lamp indicator C6 C18 Marker lamps - rear Horn C20 Interior mirror C19 Strobe light - rear \*\*\* C6 Speedometer C17 Identification - rear Brakes C4 Exhaust system (no leaks) Driver seat belt Fuel tank Tires (2/32" rear - 4/32" front min.) Steering gear Fire extinguisher (5 lbs) Cleanliness C13 First aid kit C22 Stop arm No trailer hitch C13 Body fluids kit C5 C11 Defroster Required by forest regulation: C6 Heaters Shovel (securely fastened) C20 Wheelchair forward facing (post 1993) Axe (securely fastened) \*Page number reference, Standards for School Buses in Montana (2002 Edition). \*\*\*\*Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver. 
\*\*Does not apply. \*\*\*New buses ordered after 08/15/02.\*\*\*\*\*Based on original capacity listed on the manufacturers certification tag found inside the bus. On first inspection, this bus is: On reinspection, this bus is: Approved Approved Not Approved Not Approved Inspecting Patrol Officer: Inspecting Patrol Officer: Date Date Badge No.



# **MONTANA HIGHWAY PATROL**

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

TR-13 Revised 11/04

Highway Patrol as soon as all defects are corrected.												
Instru	actions to OPI from School District	:										
This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.												
Please make corrections noted below. Don't black out the error, OPI may no												
OPI County # and County Name				Distri	ct Name							
45 Sanders						No	xon Public S					
Vehic	le I.D. # (VIN) - Entire Number		Мо	del Ye	ar	Licen	se#	Rat	ed Capacity	*****		
	1GBJ7T1JXTJ104166			199	16		42			54		
Chas	sis Make				Body Mal	ke	-12	Bus Type: (see	e ? for defin	_		
	Ol					DI.		□а □в	✓ C	$\Box$ D		
Whee	Chevrolet el Chair Lift Equipped?	Whe	el Chair	· Lift F	quipped?		ıebird					
☐ Y			orwar				<u> </u>	ot Applicable				
Туре	of Fuel:	Is B	us: 🗸	Distri	ct Owned	i	ontractor Owned If co	ontractor owned,	contractor's	name	is:	
$\Box$ G	as 🗹 Diesel 🗌 Other											
					INSPE	CTION						
		TO	BE FIL	LED			GHWAY PATROL					
	This	inspect	ion is fo	r:	1s	t semes	ster 🗹 2nd seme	ster				
		1		oved		1_			L	<del>- ' '</del>	roved	
Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in for School Bus		Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attach					+
C18	Head lamps					C18	Interior lamps				†	
C10	Color					C18	Ceiling - interior					
C18	Turn signal lamps - front					C21	Seating				<u> </u>	
C18	Turn signal lamps - side (post 1987)					C14	Floor					_
C18	Red amber signals - front  Marker lamps - front					C9 C22	Aisle Tools - storage				+	_
C18	Windshield					C24	Windows				+	-
C24	Windshield wipers					C13	Warning device					+
C20	Exterior mirrors					C13	Buzzer emergency d	oor				
C3	Battery					C12	Emergency door					
C4	Generator or alternator					C18	Red amber signals -					_
C11	Service door Head lamp indicator					C18	Turn signal lamps - re Stop lamps	ear			+	-
C6	Horn					C18	Marker lamps - rear				+	-
C20	Interior mirror					C19	Strobe light - rear ***					+
C6	Speedometer					C17	Identification - rear					
C2	Brakes					C4	Exhaust system (no l	eaks)				
C21	Driver seat belt					C5	Fuel tank	00   (1				_
C7 C13	Steering gear Fire extinguisher (5 lbs)					C7	Tires (2/32" rear - 4/3 Cleanliness	32" front min.)			+	-
C13	First aid kit					C22	Stop arm				+	-
C13	Body fluids kit					C5	No trailer hitch					+
C11	Defroster						Required by forest i	regulation:				
C6	Heaters						Shovel (securely fast					
C20	Wheelchair forward facing (post 1993)	<u> </u>	(0000 F II	\ *	****		Axe (securely fastene	,		<u> </u>		
	umber reference, Standards for School Buses in lot apply. ***New buses ordered after 08/15/02.*									driver.		
	rst inspection, this bus is:			-			einspection, this bus	-				
	Approved						Approved					
	Not Approved						Not Approved					
Inspe	cting Patrol Officer:					Inspe	cting Patrol Officer:					
Rades	- No	Date										
	No.	Date				Badge No Date						
signa	ture of District Official					Date						



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

### **MONTANA HIGHWAY PATROL**

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

TR-13 Revised 11/04

Helena, MT 59620-2501 This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected. Instructions to OPI from School District: ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records. Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction. OPI County # and County Name District Name **Noxon Public Schools** 45 Sanders Vehicle I.D. # (VIN) - Entire Number Model Year License # Rated Capacity \*\*\*\*\* 1GBL7T1J0TJ104184 1996 121 Bus Type: (see ? for definition) Chassis Make Body Make  $\Box$  A  $\Box$  B ✓ C  $\Box$  D Chevrolet **Bluebird** Wheel Chair Lift Equipped? Wheel Chair Lift Equipped? ☐ Yes ✓ No ☐ Forward Facing ☐ Aisle Facing ✓ Not Applicable Type of Fuel: Is Bus: District Owned Contractor Owned If contractor owned, contractor's name is: Gas ✓ Diesel Other INSPECTION TO BE FILLED OUT BY THE HIGHWAY PATROL 1st semester ✓ 2nd semester This inspection is for: Approved Approved Page NΑ Items listed in the Standards No NA Items listed in the Standards Yes No Yes Corr Page Corr No.\* for School Buses in Montana No.\* for School Buses in Montana Belt cutter \*\*\*\* attached C17 Identification - front C34 C18 Head lamps C18 Interior lamps C18 C10 Color Ceiling - interior Turn signal lamps - front C18 C21 Seating Turn signal lamps - side (post 1987) C14 C18 Floor C18 Red amber signals - front C9 Aisle C18 Marker lamps - front C22 Tools - storage C18 Windshield C24 Windows C24 Windshield wipers C13 Warning device C20 Exterior mirrors C13 Buzzer emergency door C3 C12 Emergency door **Battery** C4 Generator or alternator C18 Red amber signals - rear Turn signal lamps - rear C11 C18 Service door C18 Stop lamps C6Head lamp indicator C6 C18 Marker lamps - rear Horn C20 Interior mirror C19 Strobe light - rear \*\*\* C6 Speedometer C17 Identification - rear Brakes C4 Exhaust system (no leaks) Driver seat belt Fuel tank Tires (2/32" rear - 4/32" front min.) Steering gear Fire extinguisher (5 lbs) Cleanliness C13 First aid kit C22 Stop arm No trailer hitch C13 Body fluids kit C5 C11 Defroster Required by forest regulation: C6 Heaters Shovel (securely fastened) C20 Wheelchair forward facing (post 1993) Axe (securely fastened) \*Page number reference, Standards for School Buses in Montana (2002 Edition). \*\*\*\*Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver. 
\*\*Does not apply. \*\*\*New buses ordered after 08/15/02.\*\*\*\*\*Based on original capacity listed on the manufacturers certification tag found inside the bus. On first inspection, this bus is: On reinspection, this bus is: Approved Approved Not Approved Not Approved Inspecting Patrol Officer: Inspecting Patrol Officer: Date Date Badge No.



### **MONTANA HIGHWAY PATROL**

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

TR-13 Revised 11/04

Highway Patrol as soon as all defects are corrected.													
Instructions to OPI from School District:  This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.													
Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.													
OPI County # and County Name						District Name							
	45 Sanders						No	xon Publ	ic Sch	ools			
Vehic	le I.D. # (VIN) - Entire Number		Мо	del Y	ear	Licen			Rated 0		/ ****		
	1BAAHCSHXMF046143			199	91		29				71		
Chass	sis Make				Body Mal	ке		Bus Type	: (see ? f	or defin	ition)		
	Bluebird					Blu	ebird	$\Box$ A	⊒в [	□с	<b>✓</b> D		
Whee	l Chair Lift Equipped?	Whe	el Chair	Lift E	quipped?	)							
☐ Ye	es 🗹 No	□ F	orwar	d Fa	cing	☐ Aisl	e Facing 🗹 N	ot Applica	able				
Туре	of Fuel:	Is B	us: 🗸	Distri	ct Owned	d C	ontractor Owned If co			tractor's	name	s:	
									,				
☐ G	as 🗹 Diesel 🗌 Other												
					INSPE	CTION							
					OUT BY	THE HI	GHWAY PATROL						
	This	inspect	ion is fo		1s	t semes	ster 🗹 2nd semes	ster					
Page	Items listed in the Standards	Yes	Appr	oved NA	Corr	Page	Items listed in	the Stander	dc	Yes	App No	roved NA	Corr
No.*	for School Buses in Montana	168	INO	**	Con	No.*	for School Bus			168	INO	**	Con
C17	Identification - front					C34	Belt cutter **** attach	ed		1			
C18	Head lamps					C18	Interior lamps						
C10	Color					C18	Ceiling - interior						
C18	Turn signal lamps - front					C21	Seating						
C18	Turn signal lamps - side (post 1987)					C14	Floor						
C18	Red amber signals - front					C9	Aisle						
C18	Marker lamps - front		1		1	C22	Tools - storage			1	1		
C18	Windshield					C24	Windows						
C24	Windshield wipers					C13	Warning device						
C20	Exterior mirrors					C13	Buzzer emergency do	oor					
C3	Battery		1		+	C12	Emergency door	<del>, , , , , , , , , , , , , , , , , , , </del>		1			
C4	Generator or alternator		1		+	C18	Red amber signals -	rear		1			
C11	Service door				+	C18	Turn signal lamps - re						
C6	Head lamp indicator	1			_	C18	Stop lamps	Jai					
C6	Horn					C18	Marker lamps - rear						
C20	Interior mirror	1	<del> </del>		+	C19	Strobe light - rear ***			<del> </del>	<del> </del>	<b>.</b>	1
C6	Speedometer	1	<del> </del>		+	C17	Identification - rear			<del> </del>	<del> </del>	<b>.</b>	1
C2					+	C17		ooko)		1	1		
	Brakes				_		Exhaust system (no le Fuel tank	eaks)					
C21	Driver seat belt				_	C5		O" front min	`				
C7	Steering gear				_	C7	Tires (2/32" rear - 4/3	2 110111 111111	.)				
	Fire extinguisher (5 lbs)					000	Cleanliness						
C13	First aid kit	1	<u> </u>		-	C22	Stop arm			<u> </u>	<u> </u>	<u> </u>	
C13	Body fluids kit					C5	No trailer hitch						
C11	Defroster	1	<u> </u>		-		Required by forest r	_		<u> </u>	<u> </u>	<u> </u>	
C6	Heaters	1	<u> </u>		-		Shovel (securely fast	,		<u> </u>	<u> </u>	<u> </u>	
C20	Wheelchair forward facing (post 1993)	Montons	(2002 5-1	tion)	****Duc al-:	10ro 575	Axe (securely fastene		tor ottook -	d nearly	driver	<u> </u>	
**Does r	umber reference, Standards for School Buses in not apply. ***New buses ordered after 08/15/02.*	viontana ****Based	(2002 Edi d on origin	uon). al cap	acity listed	vers are r on the m	equired to wear lap/should anufacturers certification t	uer peits - cut ag found insid	ier attache de the bus	eu nearby	ariver.		
					-								
	st inspection, this bus is:					l	einspection, this bus	15:					
	Approved Not Approved						Approved Not Approved						
				• •									
Inspecting Patrol Officer:				Inspecting Patrol Officer:									
Badge		Date				Badge No Date							
Signature of District Official Date													



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Holona, MT 59620-2501

### **MONTANA HIGHWAY PATROL**

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

TR-13 Revised 11/04

Helena, MT 59620-2501 This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected. Instructions to OPI from School District: ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records. Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction. OPI County # and County Name District Name **Noxon Public Schools** 45 Sanders Vehicle I.D. # (VIN) - Entire Number Model Year License # Rated Capacity \*\*\*\*\* 1GBL7T1J8VJ110897 1997 251 Bus Type: (see ? for definition) Chassis Make Body Make  $\Box$  A  $\Box$  B ✓ C  $\Box$  D Chevrolet **Bluebird** Wheel Chair Lift Equipped? Wheel Chair Lift Equipped? ☐ Yes ✓ No ☐ Forward Facing ☐ Aisle Facing ✓ Not Applicable Type of Fuel: Is Bus: District Owned Contractor Owned If contractor owned, contractor's name is: Gas ✓ Diesel Other INSPECTION TO BE FILLED OUT BY THE HIGHWAY PATROL 1st semester ✓ 2nd semester This inspection is for: Approved Approved Page NΑ Items listed in the Standards No NA Items listed in the Standards Yes No Yes Corr Page Corr No.\* for School Buses in Montana No.\* for School Buses in Montana Belt cutter \*\*\*\* attached C17 Identification - front C34 C18 Head lamps C18 Interior lamps C18 C10 Color Ceiling - interior Turn signal lamps - front C18 C21 Seating Turn signal lamps - side (post 1987) C14 C18 Floor C18 Red amber signals - front C9 Aisle C18 Marker lamps - front C22 Tools - storage C18 Windshield C24 Windows C24 Windshield wipers C13 Warning device C20 Exterior mirrors C13 Buzzer emergency door C3 C12 Emergency door **Battery** C4 Generator or alternator C18 Red amber signals - rear Turn signal lamps - rear C11 C18 Service door C18 Stop lamps C6Head lamp indicator C6 C18 Marker lamps - rear Horn C20 Interior mirror C19 Strobe light - rear \*\*\* C6 Speedometer C17 Identification - rear Brakes C4 Exhaust system (no leaks) Driver seat belt Fuel tank Tires (2/32" rear - 4/32" front min.) Steering gear Fire extinguisher (5 lbs) Cleanliness C13 First aid kit C22 Stop arm No trailer hitch C13 Body fluids kit C5 C11 Defroster Required by forest regulation: C6 Heaters Shovel (securely fastened) C20 Wheelchair forward facing (post 1993) Axe (securely fastened) \*Page number reference, Standards for School Buses in Montana (2002 Edition). \*\*\*\*Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver. 
\*\*Does not apply. \*\*\*New buses ordered after 08/15/02.\*\*\*\*\*Based on original capacity listed on the manufacturers certification tag found inside the bus. On first inspection, this bus is: On reinspection, this bus is: Approved Approved Not Approved Not Approved Inspecting Patrol Officer: Inspecting Patrol Officer: Date Date Badge No.



# **MONTANA HIGHWAY PATROL**

**School Bus Inspection** School Year 2006

State	
District	
County	
Patrol	
Contractor	

TR-13 Revised 11/04

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the

Highway Patrol as soon as all defects are corrected.													
Instructions to OPI from School District:													
	☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records. ☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.												
	County # and County Name	DIACK OL	it trie er	ioi, OF	n may n	District Name							
						Distric							
	45 Sanders							xon Publ			***		
Vehic	le I.D. # (VIN) - Entire Number		Mc	del Ye	ar	Licen	se #		Rated C	apacity	*****		
	1G3L7T1J0TJ102757			199	6		226				72		
Chas	sis Make			E	Body Mal	ке		Bus Type	: (see ? fo	or defini	tion)		
	Chevrolet					Blu	ebird	□ A [	⊒в •	✓ C	$\Box$ D		
Whee	l Chair Lift Equipped?	Whe	el Chai	r Lift E	quipped?			I					
☐ Ye	es 🗹 No	I⊓F	orwar	d Fac	cina	Aisl	e Facing 🗹 N	ot Applica	able				
	of Fuel:						ontractor Owned If co			ractor's	name	is:	
									,				
	☐ Gas ☑ Diesel ☐ Other												
INSPECTION TO BE FILLED OUT BY THE HIGHWAY PATROL													
	TO BE FILLED OUT BY THE HIGHWAY PATROL  This inspection is for: ☐ 1st semester ✓ 2nd semester												
	11113			roved		. 0011100	Zina contro	J.01			App	roved	
Page	Items listed in the Standards	Yes	No	NA	Corr	Page	Items listed in			Yes	No	NA	Corr
No.*	for School Buses in Montana			**		No.*	for School Bus		ına			<u> </u>	
C17	Identification - front Head lamps					C34 C18	Belt cutter **** attach Interior lamps	iea				+	
C10	Color					C18	Ceiling - interior					1	
C18	Turn signal lamps - front					C21							
C18	Turn signal lamps - side (post 1987)					C14							
C18	Red amber signals - front  Marker lamps - front					C9 C22	Aisle Tools - storage					<del> </del>	
C18	Windshield					C24	Š					+	
C24	Windshield wipers					C13 Warning device							
C20	Exterior mirrors					C13	Buzzer emergency de	oor					
C3	Battery					C12	Emergency door					4	
C4 C11	Generator or alternator Service door					C18	Red amber signals - Turn signal lamps - re					+	
C6	Head lamp indicator					C18	Stop lamps	Cai				+	
C6	Horn					C18	Marker lamps - rear						
C20	Interior mirror						Strobe light - rear ***						
C6	Speedometer					C17	Identification - rear	laaka)				<del> </del>	
C2 C21	Brakes Driver seat belt					C5	Exhaust system (no I Fuel tank	eaks)				+	
C7	Steering gear					C7	Tires (2/32" rear - 4/3	32" front min	1.)				
C13	Fire extinguisher (5 lbs)						Cleanliness						
C13	First aid kit					C22	Stop arm						
C13	Body fluids kit  Defroster					C5	No trailer hitch  Required by forest i	rogulation:				+	
C6	Heaters						Shovel (securely fast					1	
C20	Wheelchair forward facing (post 1993)						Axe (securely fastene	,				1	
	umber reference, Standards for School Buses in Not apply. ***New buses ordered after 08/15/02.**									d nearby	driver.		
	est inspection, this bus is:						inspection, this bus						
	St inspection, this bus is:						Approved	13.					
	Not Approved						Not Approved						
Insped	cting Patrol Officer:					Inspec	cting Patrol Officer:						
Badge	No	Date				Badge No. Date							
	ture of District Official	_				Date Date							
-													



### **MONTANA HIGHWAY PATROL**

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

Helena, MT 59620-2501 This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected. Instructions to OPI from School District: ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records. Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction. OPI County # and County Name District Name **Noxon Public Schools** 45 Sanders Vehicle I.D. # (VIN) - Entire Number Model Year Rated Capacity \*\*\*\*\* License # 1FDNB80C8SVA53880 1995 195 Bus Type: (see ? for definition) Chassis Make Body Make ПА Пв ✓ C  $\Box$  D Ford **Amtran** Wheel Chair Lift Equipped? Wheel Chair Lift Equipped? ☐ Yes ✓ No ☐ Forward Facing ☐ Aisle Facing ✓ Not Applicable Type of Fuel: Is Bus: ✓ District Owned ☐ Contractor Owned If contractor owned, contractor's name is: Gas ✓ Diesel Other INSPECTION TO BE FILLED OUT BY THE HIGHWAY PATROL 1st semester ✓ 2nd semester This inspection is for: Approved Approved Page NΑ Items listed in the Standards Items listed in the Standards No NA Page Yes No Yes Corr Corr No.\* for School Buses in Montana No.\* for School Buses in Montana Belt cutter \*\*\*\* attached C17 Identification - front C34 C18 Head lamps C18 Interior lamps C18 C10 Color Ceiling - interior Turn signal lamps - front C18 C21 Seating Turn signal lamps - side (post 1987) C14 C18 Floor C18 Red amber signals - front C9 Aisle C18 Marker lamps - front C22 Tools - storage C18 Windshield C24 Windows C24 Windshield wipers C13 Warning device C20 Exterior mirrors C13 Buzzer emergency door C3 C12 Emergency door **Battery** C4 Generator or alternator C18 Red amber signals - rear Turn signal lamps - rear C11 C18 Service door C18 Stop lamps C6Head lamp indicator C6 C18 Marker lamps - rear Horn C20 Interior mirror C19 Strobe light - rear \*\*\* C6 Speedometer C17 Identification - rear Brakes C4 Exhaust system (no leaks) Driver seat belt Fuel tank Tires (2/32" rear - 4/32" front min.) Steering gear Fire extinguisher (5 lbs) Cleanliness C13 First aid kit C22 Stop arm No trailer hitch C13 Body fluids kit C5 C11 Defroster Required by forest regulation: C6 Heaters Shovel (securely fastened) C20 Wheelchair forward facing (post 1993) Axe (securely fastened) \*Page number reference, Standards for School Buses in Montana (2002 Edition). \*\*\*\*Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver. 
\*\*Does not apply. \*\*\*New buses ordered after 08/15/02.\*\*\*\*\*Based on original capacity listed on the manufacturers certification tag found inside the bus. On first inspection, this bus is: On reinspection, this bus is: Approved Approved

Off fell-spection, this bus is:

Approved
Not Approved
Inspecting Patrol Officer:

Badge No.

Date
Badge No.

Date

Date

TR-13 Revised 11/04



# **MONTANA HIGHWAY PATROL**

**School Bus Inspection** School Year 2006

State	
District	
County	
Patrol	
Contractor	

TR-13 Revised 11/04

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the

Highw	ay Patrol as soon as all defects are correct	ed.		,										
Instructions to OPI from School District:														
	☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records. ☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.													
	County # and County Name	DIACK OU	it trie er	IOI, OF	n may ne	District Name								
						Distric								
	45 Sanders							as Prairie						
Vehic	le I.D. # (VIN) - Entire Number		Mc	del Ye	ar	Licen	se #		Rated Ca	apacity	*****			
	1FDNJ75C2PVA25098			199	3		L21				47			
Chas	sis Make			E	Body Mal	ке		Bus Type:	(see ? fo	r defin	tion)			
	Ford					The	omas	$\Box$ A $\Box$	]В ▶	C	$\Box$ D			
Whee	l Chair Lift Equipped?	Whe	el Chai	r Lift E	quipped?									
☐ Y	es 🗹 No	│□F	orwar	d Fac	ina	Aisl	e Facing 🗹 N	lot Applica	ble					
	of Fuel:						ontractor Owned If co			actor's	name	is:		
□G									,					
	as 💌 Diesei 🗀 Othei						Manford Te	mpero						
INSPECTION TO BE FILLED OUT BY THE HIGHWAY BATROL														
TO BE FILLED OUT BY THE HIGHWAY PATROL  This inspection is for: ☐ 1st semester ✓ 2nd semester														
	11110	Порсос		roved		Como	Zila seme	otoi			App	roved		
Page	Items listed in the Standards	Yes	No	NA	Corr	Page	Items listed in		-	Yes	No	NA	Corr	
No.*	for School Buses in Montana			**	<u> </u>	No.*	for School Bus		na			**		
C17	Identification - front Head lamps					C34 C18	Belt cutter **** attach Interior lamps	ied						
C10	Color					C18	Ceiling - interior							
C18	Turn signal lamps - front					C21								
C18	Turn signal lamps - side (post 1987)					C14								
C18	Red amber signals - front					C9	Aisle							
C18	Marker lamps - front Windshield					C22 C24	Š					<u> </u>		
C24	Windshield wipers					C13								
C20	Exterior mirrors					C13	Buzzer emergency d	oor						
C3	Battery					C12	Emergency door							
C4	Generator or alternator Service door				-	C18	Red amber signals -		-					
C11 C6	Head lamp indicator					C18	Turn signal lamps - re Stop lamps	ear						
C6	Horn						Marker lamps - rear							
C20	Interior mirror						Strobe light - rear ***							
C6	Speedometer						Identification - rear							
C2	Brakes				-	C4	Exhaust system (no l	eaks)	-					
C21	Driver seat belt Steering gear					C5 C7	Fuel tank Tires (2/32" rear - 4/3	32" front min.	)					
C13	Fire extinguisher (5 lbs)					0.	Cleanliness		.,					
C13	First aid kit					C22	Stop arm							
C13	Body fluids kit					C5	No trailer hitch							
C11 C6	Defroster Heaters						Required by forest in Shovel (securely fast							
C20	Wheelchair forward facing (post 1993)						Axe (securely fastene	,						
*Page n	umber reference, Standards for School Buses in M						equired to wear lap/shoul	der belts - cutt		nearby	driver.	1	1	
**Does r	not apply. ***New buses ordered after 08/15/02.**	***Based	l on origir	nal capa	city listed	on the m	anufacturers certification	tag found insid	e the bus.					
On fi	st inspection, this bus is:					On re	inspection, this bus	is:						
	Approved						Approved							
	Not Approved						Not Approved							
Inspe	cting Patrol Officer:					Inspec	cting Patrol Officer:							
Badge	No	Date				Badge No Date								
Signa	Signature of District Official						Date							



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Holona, MT 59620-2501

### **MONTANA HIGHWAY PATROL**

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

TR-13 Revised 11/04

Helena, MT 59620-2501 This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected. Instructions to OPI from School District: ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records. Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction. OPI County # and County Name District Name **Hot Springs Public Schls** 45 Sanders Rated Capacity \*\*\*\*\* Vehicle I.D. # (VIN) - Entire Number Model Year License # 4DRBUAAP65B971252 370 2005 Bus Type: (see ? for definition) Chassis Make Body Make  $\square$  B  $\square$  C ПА **✓** D International International Wheel Chair Lift Equipped? Wheel Chair Lift Equipped? ☐ Yes ✓ No ☐ Forward Facing ☐ Aisle Facing ✓ Not Applicable Type of Fuel: Is Bus: ✓ District Owned ☐ Contractor Owned If contractor owned, contractor's name is: Gas ✓ Diesel Other INSPECTION TO BE FILLED OUT BY THE HIGHWAY PATROL 1st semester ✓ 2nd semester This inspection is for: Approved Approved Items listed in the Standards NΑ Items listed in the Standards Page No NA Page Yes No Yes Corr Corr No.\* for School Buses in Montana No.\* for School Buses in Montana Belt cutter \*\*\*\* attached C17 Identification - front C34 C18 Head lamps C18 Interior lamps C18 C10 Color Ceiling - interior Turn signal lamps - front C18 C21 Seating Turn signal lamps - side (post 1987) C14 C18 Floor C18 Red amber signals - front C9 Aisle C18 Marker lamps - front C22 Tools - storage C18 Windshield C24 Windows C24 Windshield wipers C13 Warning device C20 Exterior mirrors C13 Buzzer emergency door C3 C12 Emergency door **Battery** C4 Generator or alternator C18 Red amber signals - rear Turn signal lamps - rear C11 C18 Service door C18 Stop lamps C6Head lamp indicator C6 C18 Marker lamps - rear Horn C20 Interior mirror C19 Strobe light - rear \*\*\* C6 Speedometer C17 Identification - rear Brakes C4 Exhaust system (no leaks) Driver seat belt Fuel tank Tires (2/32" rear - 4/32" front min.) Steering gear Fire extinguisher (5 lbs) Cleanliness C13 First aid kit C22 Stop arm No trailer hitch C13 Body fluids kit C5 C11 Defroster Required by forest regulation: C6 Heaters Shovel (securely fastened) C20 Wheelchair forward facing (post 1993) Axe (securely fastened) \*Page number reference, Standards for School Buses in Montana (2002 Edition). \*\*\*\*Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver. 
\*\*Does not apply. \*\*\*New buses ordered after 08/15/02.\*\*\*\*\*Based on original capacity listed on the manufacturers certification tag found inside the bus. On first inspection, this bus is: On reinspection, this bus is: Approved Approved Not Approved Not Approved Inspecting Patrol Officer: Inspecting Patrol Officer: Date Date Badge No.



### **MONTANA HIGHWAY PATROL**

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected. Instructions to OPI from School District: ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records. Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction. OPI County # and County Name District Name **Hot Springs Public Schls** 45 Sanders Vehicle I.D. # (VIN) - Entire Number Model Year License # Rated Capacity \*\*\*\*\* 1BAAKCPAX2F202580 2002 32 72 Bus Type: (see ? for definition) Chassis Make Body Make ПА  $\square$  B **✓** D **Bluebird Bluebird** Wheel Chair Lift Equipped? Wheel Chair Lift Equipped? ☐ Yes ✓ No ✓ Not Applicable ☐ Forward Facing ☐ Aisle Facing Type of Fuel: Is Bus: ✓ District Owned ☐ Contractor Owned If contractor owned, contractor's name is: ☐ Gas ✓ Diesel Other **INSPECTION** TO BE FILLED OUT BY THE HIGHWAY PATROL 1st semester ✓ 2nd semester This inspection is for: Approved Approved Page Items listed in the Standards Page Items listed in the Standards No Yes No NA Yes NA Corr No.\* for School Buses in Montana No.\* for School Buses in Montana Belt cutter \*\*\*\* attached C17 Identification - front C34 C18 Head lamps C18 Interior lamps C10 C18 Ceiling - interior Color Turn signal lamps - front C21

C18	Turn signal lamps - side (post 1987)			C14	Floor					
C18	Red amber signals - front			C9	Aisle					
C18	Marker lamps - front			C22	Tools - storage					
C18	Windshield			C24	Windows					
C24	Windshield wipers			C13	Warning device					
C20	Exterior mirrors			C13	Buzzer emergency door					
C3	Battery			C12	Emergency door					
C4	Generator or alternator			C18	Red amber signals - rear					
C11	Service door			C18	Turn signal lamps - rear					
C6	Head lamp indicator			C18	Stop lamps					
C6	Horn			C18	Marker lamps - rear					
C20	Interior mirror			C19	Strobe light - rear ***					
C6	Speedometer			C17	Identification - rear					
C2	Brakes			C4	Exhaust system (no leaks)					
C21	Driver seat belt			C5	Fuel tank					
C7	Steering gear			C7	Tires (2/32" rear - 4/32" front min.)					
C13	Fire extinguisher (5 lbs)				Cleanliness					
C13	First aid kit			C22	Stop arm					
C13	Body fluids kit			C5	No trailer hitch					
C11	Defroster				Required by forest regulation:					
C6	Heaters				Shovel (securely fastened)					
C20	Wheelchair forward facing (post 1993)				Axe (securely fastened)					
	umber reference, Standards for School Buses in Monot apply. ***New buses ordered after 08/15/02.***						driver.			
On first inspection, this bus is:			On re	On reinspection, this bus is:						

On first inspection, this bus is:		On reinspection, this bus is:					
Approved		Approved					
Not Approved		Not Approved					
Inspecting Patrol Officer:		Inspecting Patrol Officer:					
Badge No.	Date	Badge No.	Date				
Signature of District Official		Date					
			TR-13 Revised 11/04				



### **MONTANA HIGHWAY PATROL**

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

Helena, MT 59620-2501 This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected. Instructions to OPI from School District: ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records. Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction. OPI County # and County Name District Name **Hot Springs Public Schls** 45 Sanders Vehicle I.D. # (VIN) - Entire Number Model Year Rated Capacity \*\*\*\*\* License # 1GBL7T1C22J507082 2003 5341 Bus Type: (see ? for definition) Chassis Make Body Make  $\Box$  A  $\Box$  B  $\Box$  C **✓** D Freightliner **Bluebird** Wheel Chair Lift Equipped? Wheel Chair Lift Equipped? ☐ Yes ✓ No ☐ Forward Facing ☐ Aisle Facing ✓ Not Applicable Type of Fuel: Is Bus: District Owned Contractor Owned If contractor owned, contractor's name is: Gas ✓ Diesel Other INSPECTION TO BE FILLED OUT BY THE HIGHWAY PATROL 1st semester ✓ 2nd semester This inspection is for: Approved Approved Page NΑ Items listed in the Standards Items listed in the Standards No NA Page Yes No Yes Corr Corr No.\* for School Buses in Montana No.\* for School Buses in Montana Belt cutter \*\*\*\* attached C17 Identification - front C34 C18 Head lamps C18 Interior lamps C18 C10 Color Ceiling - interior Turn signal lamps - front C18 C21 Seating Turn signal lamps - side (post 1987) C14 C18 Floor C18 Red amber signals - front C9 Aisle C18 Marker lamps - front C22 Tools - storage C18 Windshield C24 Windows C24 Windshield wipers C13 Warning device C20 Exterior mirrors C13 Buzzer emergency door C3 C12 Emergency door **Battery** C4 Generator or alternator C18 Red amber signals - rear Turn signal lamps - rear C11 C18 Service door C18 Stop lamps C6Head lamp indicator C6 C18 Marker lamps - rear Horn C20 Interior mirror C19 Strobe light - rear \*\*\* C6 Speedometer C17 Identification - rear Brakes C4 Exhaust system (no leaks) Driver seat belt Fuel tank Tires (2/32" rear - 4/32" front min.) Steering gear Fire extinguisher (5 lbs) Cleanliness C13 First aid kit C22 Stop arm No trailer hitch C13 Body fluids kit C5 C11 Defroster Required by forest regulation: C6 Heaters Shovel (securely fastened) C20 Wheelchair forward facing (post 1993) Axe (securely fastened) \*Page number reference, Standards for School Buses in Montana (2002 Edition). \*\*\*\*Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver. 
\*\*Does not apply. \*\*\*New buses ordered after 08/15/02.\*\*\*\*\*Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

Approved
Not Approved
Inspecting Patrol Officer:

Badge No.
Date
Badge No.
Date
TR-13 Revised 11/04



Linda McCulloch, Superintendent Office of Public Instruction PO Box 202501 Helena MT 59620-2501

#### **MONTANA HIGHWAY PATROL**

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

TR-13 Revised 11/04

Helena, MT 59620-2501 This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected. Instructions to OPI from School District: ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records. Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction. OPI County # and County Name District Name **Hot Springs Public Schls** 45 Sanders Vehicle I.D. # (VIN) - Entire Number Model Year Rated Capacity \*\*\*\*\* License # 1BAKGCKH35F225245 2005 367 Bus Type: (see ? for definition) Chassis Make Body Make  $\Box$  A  $\Box$  B  $\Box$  C **✓** D Freightliner **Bluebird** Wheel Chair Lift Equipped? Wheel Chair Lift Equipped? ☐ Yes ✓ No ☐ Forward Facing ☐ Aisle Facing ✓ Not Applicable Type of Fuel: Is Bus: District Owned Contractor Owned If contractor owned, contractor's name is: Gas ✓ Diesel Other INSPECTION TO BE FILLED OUT BY THE HIGHWAY PATROL 1st semester ✓ 2nd semester This inspection is for: Approved Approved NΑ Items listed in the Standards Items listed in the Standards Page No NA Page Yes No Yes Corr Corr No.\* for School Buses in Montana No.\* for School Buses in Montana Belt cutter \*\*\*\* attached C17 Identification - front C34 C18 Head lamps C18 Interior lamps C18 C10 Color Ceiling - interior Turn signal lamps - front C18 C21 Seating Turn signal lamps - side (post 1987) C14 C18 Floor C18 Red amber signals - front C9 Aisle C18 Marker lamps - front C22 Tools - storage C18 Windshield C24 Windows C24 Windshield wipers C13 Warning device C20 Exterior mirrors C13 Buzzer emergency door C3 C12 Emergency door **Battery** C4 Generator or alternator C18 Red amber signals - rear Turn signal lamps - rear C11 C18 Service door C18 Stop lamps C6Head lamp indicator C6 C18 Marker lamps - rear Horn C20 Interior mirror C19 Strobe light - rear \*\*\* C6 Speedometer C17 Identification - rear Brakes C4 Exhaust system (no leaks) Driver seat belt Fuel tank Tires (2/32" rear - 4/32" front min.) Steering gear Fire extinguisher (5 lbs) Cleanliness C13 First aid kit C22 Stop arm No trailer hitch C13 Body fluids kit C5 C11 Defroster Required by forest regulation: C6 Heaters Shovel (securely fastened) C20 Wheelchair forward facing (post 1993) Axe (securely fastened) \*Page number reference, Standards for School Buses in Montana (2002 Edition). \*\*\*\*Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver. 
\*\*Does not apply. \*\*\*New buses ordered after 08/15/02.\*\*\*\*\*Based on original capacity listed on the manufacturers certification tag found inside the bus. On first inspection, this bus is: On reinspection, this bus is: Approved Approved Not Approved **Not Approved** Inspecting Patrol Officer: Inspecting Patrol Officer: Date Date Badge No.



# **MONTANA HIGHWAY PATROL**

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

TR-13 Revised 11/04

Highw	ay Patrol as soon as all defects are correc	ted.											
	ictions to OPI from School District: s bus has been sold, retired, or is no longe		/ice. Ple	ease d	elete it fr	om OPI	's records.						
_	ase make corrections noted below. Don't							ection.					
OPI County # and County Name						District Name							
45 Sanders							Hot	Springs Pu	ıblic S	Schls			
Vehic	le I.D. # (VIN) - Entire Number		Мс	del Ye	ar	Licen		F	Rated C	apacity	****		
	XXXXXXXXXXXXX2598			199	16		732C				47		
Chas	sis Make				Body Mal	ке		Bus Type: (	see?fo	r defini			
	International					0	ther		в	□с	$\Box$ D		
Whee	l Chair Lift Equipped?	Whe	el Chair	r Lift E	quipped?		uiei						
✓ Y			orwar				e Facing	ot Applicab	lo.				
	of Fuel:	Is B					ontractor Owned If co	ot Applicab		rootor'o	nomo	io:	
		15 0	us	DISTIL	or Owner	<b>V</b> C	ontractor Owned in co	ontractor owne	a, com	iacioi s	Hallie	۵.	
□G	as 🗹 Diesel 🗌 Other						Manford Te	mpero					
					INSPE	CTION							
TO BE FILLED OUT BY THE HIGHWAY PATROL  This inspection is for: ☐ 1st semester ✓ 2nd semester													
	This	inspect			1s	t semes	ster 2nd seme	ster			Ann	royad	
Page	Items listed in the Standards	Yes	No	roved NA	Corr	Page	Items listed in	the Standards	; 1	Yes	No	roved NA	Corr
No.*	for School Buses in Montana			**		No.*	for School Bus					**	
C17	Identification - front					C34	Belt cutter **** attach	ed					
C18	Head lamps					C18	Interior lamps						
C10	Color					C18	Ceiling - interior						
C18	Turn signal lamps - front						C21 Seating					₩	
C18	Turn signal lamps - side (post 1987)					C14 Floor						-	
C18	Red amber signals - front					C9 Aisle C22 Tools - storage						_	
C18	Marker lamps - front					ů .						<del> </del>	
C18	Windshield winers					C24 Windows						+	
C24 C20	Windshield wipers  Exterior mirrors					C13	C13 Warning device					+	
C20	Battery	1				C12	Buzzer emergency do Emergency door	JOI			<del> </del>	+	
C4	Generator or alternator					C18	Red amber signals -	rear				+	
C11	Service door					C18	Turn signal lamps - re				1	+	
C6	Head lamp indicator					C18	Stop lamps	<u> </u>				1	
C6	Horn					C18	Marker lamps - rear					1	
C20	Interior mirror					C19	Strobe light - rear ***					1	
C6	Speedometer					C17	Identification - rear					1	
C2	Brakes					C4	Exhaust system (no l	eaks)				1	
C21	Driver seat belt					C5	Fuel tank					1	
C7	Steering gear					C7	Tires (2/32" rear - 4/3	2" front min.)					
C13	Fire extinguisher (5 lbs)						Cleanliness						
C13	First aid kit					C22	Stop arm						
C13	Body fluids kit					C5	No trailer hitch						
C11	Defroster						Required by forest r	_				<b>↓</b>	
C6	Heaters						Shovel (securely fast						
C20	Wheelchair forward facing (post 1993)		(2222 = 1	\ .	****		Axe (securely fastene				<u> </u>		
	umber reference, Standards for School Buses in I not apply. ***New buses ordered after 08/15/02.**									a nearby	ariver.		
	rst inspection, this bus is:						einspection, this bus						
	Approved						Approved						
H	Not Approved					ΙĦ	Not Approved						
	eting Patrol Officer:					Inspe	cting Patrol Officer:						
-		Date											
Badge		Date				_	; NU.			Date			
əigna	ture of District Official					Date							



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena MT 59620-2501

### **MONTANA HIGHWAY PATROL**

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

TR-13 Revised 11/04

Helena, MT 59620-2501 This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected. Instructions to OPI from School District: This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records. Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction. OPI County # and County Name District Name **Hot Springs Public Schls** 45 Sanders Vehicle I.D. # (VIN) - Entire Number Model Year Rated Capacity \*\*\*\*\* License # 160G XXXXXXXXXXXXX3738 1993 Bus Type: (see ? for definition) Chassis Make Body Make  $\Box$  A  $\Box$  B ✓ C  $\Box$  D Ford **Amtran** Wheel Chair Lift Equipped? Wheel Chair Lift Equipped? ☐ Yes ✓ No ✓ Not Applicable ☐ Forward Facing ☐ Aisle Facing Type of Fuel: Is Bus: District Owned Contractor Owned If contractor owned, contractor's name is: Gas ✓ Diesel Other **Manford Tempero** INSPECTION TO BE FILLED OUT BY THE HIGHWAY PATROL 1st semester This inspection is for: Approved Approved Page NΑ Items listed in the Standards Items listed in the Standards No NA Yes No Yes Corr Page Corr No.\* for School Buses in Montana No.\* for School Buses in Montana Belt cutter \*\*\*\* attached C17 Identification - front C34 C18 Head lamps C18 Interior lamps C18 Ceiling - interior C10 Color Turn signal lamps - front C18 C21 Seating Turn signal lamps - side (post 1987) C14 C18 Floor C18 Red amber signals - front C9 Aisle C18 Marker lamps - front C22 Tools - storage C18 Windshield C24 Windows C24 Windshield wipers C13 Warning device C20 Exterior mirrors C13 Buzzer emergency door C3 C12 Emergency door **Battery** C4 Generator or alternator C18 Red amber signals - rear Turn signal lamps - rear C11 C18 Service door C18 Stop lamps C6Head lamp indicator C6 C18 Marker lamps - rear Horn C20 Interior mirror C19 Strobe light - rear \*\*\* C6 Speedometer C17 Identification - rear Brakes C4 Exhaust system (no leaks) Driver seat belt Fuel tank Tires (2/32" rear - 4/32" front min.) Steering gear Fire extinguisher (5 lbs) Cleanliness C13 First aid kit C22 Stop arm No trailer hitch C13 Body fluids kit C5 C11 Defroster Required by forest regulation: C6 Heaters Shovel (securely fastened) C20 Wheelchair forward facing (post 1993) Axe (securely fastened) \*Page number reference, Standards for School Buses in Montana (2002 Edition). \*\*\*\*Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver. 
\*\*Does not apply. \*\*\*New buses ordered after 08/15/02.\*\*\*\*\*Based on original capacity listed on the manufacturers certification tag found inside the bus. On first inspection, this bus is: On reinspection, this bus is: Approved Approved Not Approved **Not Approved** Inspecting Patrol Officer: Inspecting Patrol Officer: Date Date Badge No.



Date

Signature of District Official

### **MONTANA HIGHWAY PATROL**

School Bus Inspection School Year 2006

State	
District	
County	
Patrol	
Contractor	

Helena, MT 59620-2501 This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected. Instructions to OPI from School District: ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records. Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction. OPI County # and County Name District Name **Hot Springs Public Schls** 45 Sanders Vehicle I.D. # (VIN) - Entire Number Model Year Rated Capacity \*\*\*\*\* License # 1HVBBPPP2NH467258 1992 109 Bus Type: (see ? for definition) Chassis Make Body Make  $\Box$  A  $\Box$  B ✓ C  $\Box$  D International **Thomas** Wheel Chair Lift Equipped? Wheel Chair Lift Equipped? ☐ Yes ✓ No ☐ Forward Facing ☐ Aisle Facing ✓ Not Applicable Type of Fuel: Is Bus: ✓ District Owned ☐ Contractor Owned If contractor owned, contractor's name is: Gas ✓ Diesel Other INSPECTION TO BE FILLED OUT BY THE HIGHWAY PATROL 1st semester ✓ 2nd semester This inspection is for: Approved Approved NΑ Items listed in the Standards Items listed in the Standards Page No NA Page Yes No Yes Corr Corr No.\* for School Buses in Montana No.\* for School Buses in Montana Belt cutter \*\*\*\* attached C17 Identification - front C34 C18 Head lamps C18 Interior lamps C18 Ceiling - interior C10 Color Turn signal lamps - front C18 C21 Seating Turn signal lamps - side (post 1987) C14 C18 Floor C18 Red amber signals - front C9 Aisle C18 Marker lamps - front C22 Tools - storage C18 Windshield C24 Windows C24 Windshield wipers C13 Warning device C20 Exterior mirrors C13 Buzzer emergency door C3 C12 Emergency door **Battery** C4 Generator or alternator C18 Red amber signals - rear Turn signal lamps - rear C11 C18 Service door C18 Stop lamps C6Head lamp indicator C6 C18 Marker lamps - rear Horn C20 Interior mirror C19 Strobe light - rear \*\*\* C6 Speedometer C17 Identification - rear Brakes C4 Exhaust system (no leaks) Driver seat belt Fuel tank Tires (2/32" rear - 4/32" front min.) Steering gear Fire extinguisher (5 lbs) Cleanliness C13 First aid kit C22 Stop arm No trailer hitch C13 Body fluids kit C5 C11 Defroster Required by forest regulation: C6 Heaters Shovel (securely fastened) C20 Wheelchair forward facing (post 1993) Axe (securely fastened) \*Page number reference, Standards for School Buses in Montana (2002 Edition). \*\*\*\*Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver. 
\*\*Does not apply. \*\*\*New buses ordered after 08/15/02.\*\*\*\*\*Based on original capacity listed on the manufacturers certification tag found inside the bus. On first inspection, this bus is: On reinspection, this bus is: Approved Approved Not Approved **Not Approved** Inspecting Patrol Officer: Inspecting Patrol Officer:

Badge No.

Date

TR-13 Revised 11/04